

License No. SUB-1010
Docket No. 40-8027

7/6/77

Notice of Violation

Based on the results of the NRC inspection conducted on June 15, 16 and 17, 1977, certain activities appear to be in noncompliance with NRC regulations and the conditions of your NRC License No. SUB-1010 as indicated below:

1. Contrary to License Condition 8 which requires use in accordance with procedures submitted with the license application, monthly inspections of health physics programs were not conducted as required by procedures described in Annex A, pages 10 and 11 of these procedures.

This is an infraction.

2. Contrary to 10 CFR 20.203(b), each radiation area, defined in 10 CFR 20.202(b)(2), was not posted with a sign or signs bearing the radiation caution symbol and the words: "Caution Radiation Area."

This is a deficiency.

8512170070 770706
PDR ADOCK 04008027
C PDR