

CRANE

MIDWEST FITTINGS

TELEPHONE (314) 621-8300
TELEX 44-7130
TWX 1-910-761-1109

CRANE CO. • 1450 SO. SECOND STREET • P.O. BOX 433 • ST. LOUIS, MO. 63166

November 27, 1985

Mr. John R. Madera
Material Licensing Section, Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

REFERENCE: Crane Midwest Fittings Temporary Material License No. 24-00563-02
Amendment No. 22
Control No. 79587
Crane Letter Dated August 13, 1985

Dear Mr. Madera:

In accordance with our application for license renewal and letter dated August 13, 1985, attached find our revised Operating and Emergency Procedures.

The items needing clarification in your letter dated April 19, 1985 have all been incorporated in our Operating and Emergency Procedures, including No. 4, "SURVEYS". Since completion of our booth on November 25th a survey has been made and the results are as shown in Section IV of our Operating and Emergency Procedures.

Enclosed for your information are several photographs showing the cubical configuration.


We believe we are in compliance with all requirements necessary for the license renewal requested.

If additional information is needed please call the undersigned.

Very truly yours,

CRANE MIDWEST FITTINGS

8602240102 851217
REG3 LIC30
24-00563-02 PDR


George W. Eckert
Radiation Safety Officer

ENCL. Operating and Emergency Procedures (2)

cc: J. F. Bringer
J. J. Mueller
D. F. Betz
(0781A)
H. W. Palm

RECEIVED
DEC 2 1985
REGION III