

**BWRVIP**BWR Vessel &  
Internals Project

Issue Management and Resolution

**MEMORANDUM**

June 16, 1997

Document Control Desk  
U. S. Nuclear Regulatory Commission  
11555 Rockville Pike  
Rockville, MD 20852

Attention: C. E. Carpenter


Subject: Proprietary version of "Configurations of Safety-Related BWR Reactor  
Internals (BWRVIP-15)", March, 1996

On April 29, 1997 members of the BWRVIP Assessment Committee presented the results of the BWRVIP Safety Assessment Report (BWRVIP-06) to the NRC at a meeting in San Jose, CA. During this meeting the NRC requested copies of the above-referenced report. In response to this request, please find two copies of the above-referenced report. These copies are being provided for information only to support your completion of the BWRVIP-06 safety evaluation.

Please note that the enclosed proprietary document contains proprietary information. A letter requesting the report be withheld from public disclosure and affidavits describing the basis for withholding this information are provided as Attachment 1.

If you have any questions on this subject please call Robin Dyle, BWRVIP Repair Committee Chairman, Southern Nuclear, at (205) 992-7121.

Sincerely,

Carl Terry  
Niagara Mohawk Power Company  
Chairman, BWR Vessel and Internals Project

Enclosure

9706230332 970616  
PDR TOPRP EMVBW  
C PDRChange: LTA ENCL  
PDR 1 1/2  
NIAA 1 1/2  
RD-10-1

Good

1/2



T690017