

40-6659

Petrotomics Company

P. O. Box 8509, Shirley Basin, Wyoming 82615 - Telephone: (307) 234-9341

June 12, 1997

Mr. Joseph J. Holonich, Chief
Uranium Recovery Branch MS-T-7-J-9
Division of Waste Management
Office of Nuclear Material Safety
and Safeguards
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Reference: License Condition 47D,
Source Material License SUA-551.

Dear Mr. Holonich:

In accordance with the requirements of License Condition 47D, submitted herewith in triplicate is our report which reviews the corrective action program and its effect on the aquifer.

Sincerely,

R. A. Juday
R. A. Juday
Supervisor

Enclosure: Review of Corrective Action

pc: U.S. Nuclear Regulatory Commission
Region IV
Attn: Ross A. Scarano, Director
Division of Radiation Safety and Safeguards
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

NLOS

1/1



9706240168 970612
PDR ADDCK 04006659
PDR

240056