



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001

May 15, 1997

Mr. Oliver D. Kingsley, Jr.
President, TVA Nuclear and
Chief Nuclear Officer
Tennessee Valley Authority
6A Lookout Place
1101 Market Street
Chattanooga, TN 37402-2801

SUBJECT: COMPLETION OF LICENSING ACTION FOR GENERIC LETTER 95-03,
"CIRCUMFERENTIAL CRACKING OF STEAM GENERATOR TUBES," DATED
APRIL 28, 1995, FOR SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2
(TAC NOS. M92274 AND M92275)

Dear Mr. Kingsley:

On April 28, 1995, the U.S. Nuclear Regulatory Commission (NRC) issued Generic Letter (GL) 95-03, "Circumferential Cracking of Steam Generator Tubes," to all holders of operating licenses or construction permits for pressurized-water reactors. The NRC issued GL 95-03 for three principal reasons:

- (1) Notify addressees about the safety significance of the recent steam generator tube inspection findings at Maine Yankee Atomic Power Station.
- (2) Request that all addressees implement the actions described within the generic letter.
- (3) Require that all addressees submit to the NRC a written response regarding implementation of the requested actions.

In addition, GL 95-03 alerted addressees to the importance of performing comprehensive examinations of steam generator tubes using techniques and equipment capable of reliably detecting the types of degradation to which the steam generator tubes may be susceptible. The staff also noted that the performance of steam generator tube examinations is controlled, in part, by Appendix B to Title 10, Part 50, of the *Code of Federal Regulations* (10 CFR Part 50).

In GL 95-03, the NRC staff also requested that licensees take the following actions:

- (1) Evaluate recent operating experience with respect to the detection and sizing of circumferential indications to determine the applicability to their plants.
- (2) On the basis of the evaluation in Item (1) above, as well as past inspection scope and results, susceptibility to circumferential

9705160181 970515
PDR ADOCK 05000327
P PDR

NRC FILE CENTER COPY

DF01
1/0

cracking, threshold of detection, expected or inferred crack growth rates, and other relevant factors, develop a safety assessment justifying continued operation until the next scheduled steam generator tube inspections.

- (3) Develop plans for the next steam generator tube inspections as they pertain to the detection of circumferential cracking. The inspection plans should address, but not be limited to, scope (including sample expansion criteria, if applicable), methods, equipment, and criteria (including personnel training and qualification).

To document the outcome of these actions, the NRC staff requested that addressees prepare and submit the following:

- (1) A safety assessment justifying continued operation, predicated on the evaluation performed in accordance with requested actions 1 and 2 (above).
- (2) A summary of the inspection plans developed in accordance with requested action 3 (above) and a schedule for the next planned inspection.

In response to GL 95-03, you provided letters dated June 27, 1995 for the Sequoyah Nuclear Plant. This submittal provided the information requested by GL 95-03; therefore TAC Nos. M92274 and M92275 are closed. For your information, the staff's findings regarding this issue are contained in NUREG-1604, "Circumferential Cracking of Steam Generator Tubes."

If you have any questions regarding this matter, please contact me at (301) 415-2010.

Sincerely,

Original Signed by

Ronald W. Hernan, Senior Project Manager
Project Directorate II-3
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Docket Nos. 50-327 and 50-328

cc: See next page

DISTRIBUTION

Docket File
PUBLIC
SQN Reading
S. Varga
F. Hebdon
B. Clayton

OGC
ACRS
J. Johnson, RII
R. Hernan
S. Dembeck
K. Karwoski

DOCUMENT NAME: G:\SQN\92774.LTR

To receive a copy of this document, indicate in the box C=Copy w/o attachment/enclosure E=Copy with attachment/enclosure N = No copy

OFFICE	PM:PD2-3	E	LA:PD2-3	E	D:PD2-3	C
NAME	RHernan	BClayton	FHebdon			
DATE	5/13/97	5/14/97	5/15/97			

OFFICIAL RECORD COPY

Mr. Oliver D. Kingsley, Jr.
Tennessee Valley Authority

cc:

Mr. O. J. Zeringue, Sr. Vice President
Nuclear Operations
Tennessee Valley Authority
6A Lookout Place
1101 Market Street
Chattanooga, TN 37402-2801

Mr. Jack A. Bailey, Vice President
Engineering & Technical Services
Tennessee Valley Authority
6A Lookout Place
1101 Market Street
Chattanooga, TN 37402-2801

Mr. R. J. Adney, Site Vice President
Sequoyah Nuclear Plant
Tennessee Valley Authority
P.O. Box 2000
Soddy Daisy, TN 37379

General Counsel
Tennessee Valley Authority
ET 10H
400 West Summit Hill Drive
Knoxville, TN 37902

Mr. Raul R. Baron, General Manager
Nuclear Assurance and Licensing
Tennessee Valley Authority
4J Blue Ridge
1101 Market Street
Chattanooga, TN 37402-2801

Mr. Pedro Salas, Manager
Licensing and Industry Affairs
Tennessee Valley Authority
4J Blue Ridge
1101 Market Street
Chattanooga, TN 37402-2801

Mr. Ralph H. Shell, Manager
Licensing and Industry Affairs
Sequoyah Nuclear Plant
Tennessee Valley Authority
P.O. Box 2000
Soddy Daisy, TN 37379

SEQUOYAH NUCLEAR PLANT

Mr. J. T. Herron, Plant Manager
Sequoyah Nuclear Plant
Tennessee Valley Authority
P.O. Box 2000
Soddy Daisy, TN 37379

Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
61 Forsyth Street, SW., Suite 23T85
Atlanta, GA 30303-3415

Mr. Melvin C. Shannon
Senior Resident Inspector
Sequoyah Nuclear Plant
U.S. Nuclear Regulatory Commission
2600 Igou Ferry Road
Soddy Daisy, TN 37379

Mr. Michael H. Mobley, Director
Division of Radiological Health
3rd Floor, L and C Annex
401 Church Street
Nashville, TN 37243-1532

County Executive
Hamilton County Courthouse
Chattanooga, TN 37402-2801