

50-4113



UNITED STATES
NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

May 16, 1997

Mr. William R. McCollum
Site Vice President
Catawba Nuclear Station
Duke Power Company
4800 Concord Road
York, South Carolina 29745-9635

SUBJECT: CATAWBA NUCLEAR STATION - COMPLETION OF LICENSING ACTION FOR GENERIC LETTER 95-03, "CIRCUMFERENTIAL CRACKING OF STEAM GENERATOR TUBES," DATED APRIL 28, 1995 (TAC M92231 AND M92232)

Dear Mr. McCollum:

On April 28, 1995, the U.S. Nuclear Regulatory Commission (NRC) issued Generic Letter (GL) 95-03, "Circumferential Cracking of Steam Generator Tubes," to all holders of operating licenses or construction permits for pressurized-water reactors. The NRC issued GL 95-03 for three principal reasons:

- (a) Notify addressees about the safety significance of the recent steam generator tube inspection findings at Maine Yankee Atomic Power Station.
- (b) Request that all addressees implement the actions described within the generic letter.
- (c) Require that all addressees submit to the NRC a written response regarding implementation of the requested actions.

In addition, GL 95-03 alerted addressees to the importance of performing comprehensive examinations of steam generator tubes using techniques and equipment capable of reliably detecting the types of degradation to which the steam generator tubes may be susceptible. The staff also noted that the performance of steam generator tube examinations is controlled, in part, by Appendix B to Title 10, Part 50, of the *Code of Federal Regulations* (10 CFR Part 50).

In GL 95-03, the NRC staff also requested that licensees take the following actions:

- (1) Evaluate recent operating experience with respect to the detection and sizing of circumferential indications to determine the applicability to their plants.
- (2) On the basis of such evaluation, as well as past inspection scope and results, susceptibility to circumferential cracking, threshold of detection, expected or inferred crack growth rates, and other relevant factors, develop a safety assessment justifying continued operation until the next scheduled steam generator tube inspections.

200105

NRC FILE CENTER COPY

9705200297 970516
PDR ADOCK 05000413
P PDR

May 16, 1997

- (3) Develop plans for the next steam generator tube inspections as they pertain to the detection of circumferential cracking. The inspection plans should address, but not be limited to, scope (including sample expansion criteria, if applicable), methods, equipment, and criteria (including personnel training and qualification).

To document the outcome of these actions, the NRC staff requested that addressees prepare and submit the following:

- (1) A safety assessment justifying continued operation, predicated on the evaluation performed in accordance with requested actions 1 and 2 (above).
- (2) A summary of the inspection plans developed in accordance with requested action 3 (above) and a schedule for the next planned inspection.

In response to GL 95-03, Duke Power Company provided letters dated June 27, September 19, and October 25, 1995, for the Catawba Nuclear Station. These submittals provided the information requested by GL 95-03; therefore, the above TAC numbers are closed. For your information, the staff's findings regarding this issue are contained in NUREG-1604, "Circumferential Cracking of Steam Generator Tubes."

If you have any questions regarding this matter, please contact me at 301-415-1451.

Sincerely,

ORIGINAL SIGNED BY:

Peter S. Tam, Senior Project Manager
Project Directorate II-2
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Docket Nos. 50-413 and 50-414

cc: See next page

Distribution

Docket File	OGC
PUBLIC	JJohnson, RII
PDII-2 Reading	PPatnaik, O-7 E23
SVarga	CCasto, RII

DOCUMENT NAME: G:\CATAWBA\CAT92231.LTR

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	DRPE/PDII-2/PN	PDII-2/LA	PDII-2/ND						
NAME	PTam:cn	LBerry	HBerkow						
DATE	05/16/97	05/16/97	04/16/97						

OFFICIAL RECORD COPY

- (3) Develop plans for the next steam generator tube inspections as they pertain to the detection of circumferential cracking. The inspection plans should address, but not be limited to, scope (including sample expansion criteria, if applicable), methods, equipment, and criteria (including personnel training and qualification).


To document the outcome of these actions, the NRC staff requested that addressees prepare and submit the following:

- (1) A safety assessment justifying continued operation, predicated on the evaluation performed in accordance with requested actions 1 and 2 (above).
- (2) A summary of the inspection plans developed in accordance with requested action 3 (above) and a schedule for the next planned inspection.

In response to GL 95-03, Duke Power Company provided letters dated June 27, September 19, and October 25, 1995, for the Catawba Nuclear Station. These submittals provided the information requested by GL 95-03; therefore, the above TAC numbers are closed. For your information, the staff's findings regarding this issue are contained in NUREG-1604, "Circumferential Cracking of Steam Generator Tubes."

If you have any questions regarding this matter, please contact me at 301-415-1451.

Sincerely,



Peter S. Tam, Senior Project Manager
Project Directorate II-2
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Docket Nos. 50-413 and 50-414

cc: See next page

Catawba Nuclear Station
Units 1 and 2

cc:

Mr. M. S. Kitlan
Regulatory Compliance Manager
Duke Power Company
4800 Concord Road
York, South Carolina 29745

Mr. Paul R. Newton
Legal Department (PB05E)
422 South Church Street
Charlotte, North Carolina 28242-0001

J. Michael McGarry, III, Esquire
Winston and Strawn
1400 L Street, NW
Washington, DC 20005

North Carolina Municipal Power
Agency Number 1
1427 Meadowood Boulevard
P. O. Box 29513
Raleigh, North Carolina 27626-0513

Mr. T. Richard Puryear
Owner's Group (NCEMC)
Duke Power Company
4800 Concord Road
York, South Carolina 29745

County Manager of York County
York County Courthouse
York, South Carolina 29745

Richard P. Wilson, Esquire
Assistant Attorney General
South Carolina Attorney General's
Office
P. O. Box 11549
Columbia, South Carolina 29211

Piedmont Municipal Power Agency
121 Village Drive
Greer, South Carolina 29651

Dayne H. Brown, Director
Division of Radiation Protection
N.C. Department of Environment,
Health and Natural Resources
P. O. Box 27687
Raleigh, North Carolina 27611-7687

North Carolina Electric Membership
Corporation
P. O. Box 27306
Raleigh, North Carolina 27611

Senior Resident Inspector
Route 2, Box 179 N
York, South Carolina 29745

Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
Atlanta Federal Center
61 Forsyth Street, S.W., Suite 23T85
Atlanta, Georgia 30303

Max Batavia, Chief
Bureau of Radiological Health
South Carolina Department of
Health and Environmental Control
2600 Bull Street
Columbia, South Carolina 29201

Mr. G. A. Copp
Licensing - EC050
Duke Power Company
526 South Church Street
Charlotte, North Carolina 28242-0001

Saluda River Electric
P. O. Box 929
Laurens, South Carolina 29360

Ms. Karen E. Long
Assistant Attorney General
North Carolina Department of Justice
P. O. Box 629
Raleigh, North Carolina 27602

Elaine Wathen, Lead REP Planner
Division of Emergency Management
116 West Jones Street
Raleigh, North Carolina 27603-1335

Mr. William R. McCollum
Site Vice President
Catawba Nuclear Station
Duke Power Company
4800 Concord Road
York, South Carolina 29745