

APPENDIX A

NOTICE OF VIOLATION

University of Florida  
Training Reactor (UFTR)

License No. R-56

Based on the results of the NRC inspection conducted on August 16-17, 1978, it appears that certain of your activities were not conducted in full compliance with NRC regulations and commitments of your approved security plan as indicated below. The item has been categorized as described in our correspondence to you dated December 31, 1974.

Part II,C,1 of the UFTR Physical Security Plan, dated September 15, 1976, requires the reactor keys to be locked in the key cabinet when the reactor is not in operation.

Contrary to the above, on August 17, 1978, at approximately 9:30 am, the inspector observed a reactor key inserted in the console while the reactor was in a shutdown mode. No reactor operator was present at the console.

This is an infraction.

7810110201