

**LICENSEE EVENT REPORT**

EXHIBIT A

CONTROL BLOCK: 

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	A	R	S	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5			
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	37	CAT		50

CON'T

REPORT SOURCE: L 6 0 5 0 0 0 3 1 2 7 0 9 1 1 2 7 18 8 1 0 0 5 7 18 9

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

BUCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During start tests following maintenance, P-996, the Diesel Driven Fire  
03 Pump, tripped on overspeed. An investigation revealed the engine to pump  
04 coupling bolts had sheared. Contrary to T.S., only one high pressure  
05 pump was available at that time. The redundant motor-driven pump, P-440,  
06 was available at all times during the occurrence.

07 \_\_\_\_\_

08 \_\_\_\_\_

7 8 9

SYSTEM CODE A B 11		CAUSE CODE B 12		CAUSE SUBCODE C 13		COMPONENT CODE M E C F U N 14				COMP. SUBCODE Z 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 17		EVENT YEAR 7 8 21 22		SEQUENTIAL REPORT NO. 1 0 0 9 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE 1 30		REVISION NO. b 32			
ACTION TAKEN A 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 40		ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM SUB. Y 24	
PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER K 2 0 0 0 26											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)

10 The probable cause was overtightening of the coupling bolts during initial  
11 installation. The bolts were replaced, proper alignment verified, and the  
12 torque values on replacement bolts verified to not exceed recommended  
13 value.  
14

7		8		9		FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
1		5		E		38		1		0		0		30		NA	
8		9		10		11		12		13		44		45		46	
1		6		Z		33		34		35		36		37		38	
7		8		9		10		11		12		13		14		15	
1		7		0		0		0		1		Z		39		40	
7		8		9		10		11		12		13		14		15	
1		8		0		0		0		43		44		45		46	
7		8		9		10		11		12		13		14		15	
1		9		Z		42		43		44		45		46		47	
7		8		9		10		11		12		13		14		15	

PUBLICITY  
ISSUED DESCRIPTION (45) NRC USE ONLY  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
2 0 Y 34 Local newspaper and wire service 9-21-78

NAME OF PREPARER R. W. Colombo

PHONE: (916)<sup>68</sup><sup>69</sup> 452-3211

7810130190