



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

PDR

OCT 5 1978

Consolidated Papers, Inc.
Research and Development
ATTN: Mr. D. H. Middleton
Engineering Division
P. O. Box 50
Wisconsin Rapids, WI 54494

License No. 48-01117-01

Gentlemen:

This refers to the inspection conducted by Mr. J. W. Hiatt of this office on September 12, 1978, of activities authorized by NRC Byproduct Material License No. 48-01117-01 and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of non-compliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

7810130 234
~~240~~


Consolidated Papers, Inc.

- 2 -

OCT 3 1973

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



A. B. Davis, Chief
Fuel Facility and Materials
Safety Branch

Enclosure: Appendix A,
Notice of Violation

cc w/encl:
Central Files
Reproduction Unit NRC 20b
PDR
NSIC