

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I	L	Z	I	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5					
7	8	9	LICENSER CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	31	CAT 58				

CON'T

REPORT SOURCE	L	G	0	5	0	0	0	2	9	5	7	1	1	0	6	7	8	9	1	2	0	6	7	8	9
	60	61	ROCKET NUMBER					63	69	EVENT DATE					74	75	REPORT DATE					80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During routine startup operations, it was discovered that the Unit 1 Purge
0 3 Exhaust Rad. monitor, 1RTPR09, was incorrectly valved in from 10/31 through
0 4 11/6. Three containment vents, quantified prior to release, were made during
0 5 this period. Containment Ventilation Rad. monitor 1RE0011/1RE0012 which
0 6 actuates containment vent isolation was in service. Rad. monitor 1RTPR09 is
0 7 not used to quantify releases but Tech Spec 3.14.1. requires that it be
0 8 operable. There were no safety implications involved.

09		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE																	
7	8	M	C	11	A	12	X	13	V	A	L	V	E	X	14	A	15	G	16												
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.																					
17	7	8	21	22	23	1	2	9	24	25	26	27	0	3	28	29	30	L	31	0	32										
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER															
33	X	34	X	35	Z	36	Z	37	0	0	0	0	38	N	39	N	40	A	41	N	42	3	43	0	44	5	45	0	46	5	47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 When the improper valve line-up was discovered, it was immediately

1 1 corrected. The identification of personnel involved and the cause of the

1 2 event could not be determined. The control indication of radiation

1 3 monitor instrumentation failures is being gated. No further

corrective action is necessary.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
1	5	C	20	0	3	6	20	NA	B	31	Rad. monitor surveillance

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 35 3 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	2	30	NA		

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	NA

1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5															

7 8 9 10
PUBLICITY
7812210219
NRC USE ONLY
2 0 [N] (44) NA

NAME OF PREPARED: Glenn Trzyna

PHONE: 312/746-2084 ext. 233