



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76011

September 11, 1978

License No. 35-17259-01

Sooner X-Ray and Mag, Inc.  
ATTN: Homer A. McCoy  
President  
1224 South Joplin  
Tulsa, Oklahoma 74112

Gentlemen:

This refers to the inspection conducted by Messrs. Lorenzo Wilborn and Harry C. Harrison of this office, on August 31, 1978, of the activities authorized by NRC Byproduct Material License No. 35-17259-01, and to the discussion of our findings held by Mr. Wilborn with Messrs. Homer A. McCoy and Robert Budgick on August 31, 1978.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements and observations by the inspector.

Messrs. Wilborn and Harrison also reviewed the action you had taken with respect to three items of noncompliance observed during our previous inspection, which was conducted August 24, 1977. They verified that the corrective action with respect to these items was implemented as stated in your replies of September 28 and October 18, 1977 to our letters dated September 13 and October 14, 1977, respectively.

Based on the results of this inspection, it appears that one of your activities was not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith. This item of noncompliance has been categorized into the level as described in the correspondence to you dated December 31, 1974.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within twenty (20) days of your receipt of this notice, a written statement or explanation in reply including (1) corrective actions which have been taken by you and the results achieved; (2) corrective actions which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved.

7810200260

Sooner X-Ray and Mag, Inc.

-2-

September 11, 1978

Should you have any questions concerning this letter, please let me know.

Sincerely,

*R. J. Everett for*

Glen D. Brown, Chief  
Fuel Facility and Material  
Safety Branch

Enclosure:  
Notice of Violation