

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-295/88008(DRSS); 50-304/88009(DRSS)

Docket Nos. 50-295; 50-304

Licenses No. DPR-39; DPR-48

Licensee: Commonwealth Edison Company
P. O. Box 767
Chicago, IL 60690

Facility Name: Zion Nuclear Station, Units 1 and 2


Inspection At: Zion Station, Zion, Illinois

Inspection Conducted: February 1 (onsite) through
February 19, 1988 (Region III office)


Type of Inspection: Routine Security Inspection

Date of Last Security Inspection November 16-20, 1987

Inspectors:



S. Hare
Licensing Examiner

03-02-88
Date


B. Drouin
Physical Security Inspector

3/1/88
Date

Approved By:


James R. Creed, Chief
Safeguards Section

3/2/88
Date

Inspection Summary

Inspection on February 1 through 19, 1988 (Reports No. 50-295/88008(DRSS);
No. 50-304/88009(DRSS))

Areas Inspected: The special inspection reviewed the circumstances surrounding
the inadequate search of packaged material which was observed on February 1, 1988.

Results: One violation was identified and is described below:

Access Control Packages: A package entering the Protected Area was not
searched as required.

(Details: UNCLASSIFIED SAFEGUARDS INFORMATION)

8803C30154 880303
PDR ADOCK 05000295
G PDR

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled