

March 4, 1994

Florida Power Corporation
Crystal River Energy Complex
Mr. Roy A. Anderson (SA2A)
Sr. VP, Nuclear Operations
ATTN: Mgr., Nuclear Licensing
15760 West Power Line Street
Crystal River, FL 34428-6708

SUBJECT: SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE (SALP)
(NRC INSPECTION REPORT NO. 50-302/96-99)

Dear Mr. Anderson:

Thank you for your response of December 20, 1996, to our SALP Report issued on November 25, 1996, concerning the performance of Plant Operations, Maintenance, Engineering and Plant Support activities at your Crystal River facility. We understand that your overall corrective actions to achieve improved plant performance include: a number of organizational and personnel changes, emphasis on the clear communication of expectations and standards with continuing accountability to these high standards, commitment to improve design margin as represented by the current shutdown and a comprehensive readiness for restart program, and the continuing implementation of your Management Corrective Action Plan (MCAP II). We continue to emphasize that your corrective actions must be complimented by an adequate performance measurements program to assure that your corrective actions are effective in improving overall performance.

We will evaluate your corrective actions and resolution of restart issues through a combination of enhanced inspections and the guidelines established in Manual Chapter 0350 "Staff Guidelines for Restart Approval." Additionally, we will continue to inspect and assess your ongoing efforts to use MCAP II to facilitate improvement in each functional area.

We appreciate your response and attention to the assessment results.


Sincerely,

Original signed by Luis A. Reyes

Luis A. Reyes
Regional Administrator

Docket No. 50-302
License No. DPR-72

9703280045 970304
PDR ADOCK 05000302
G PDR



1240

cc: John P. Cowan, Vice President
Nuclear Production (SA2C)
FPC, Crystal River Energy Complex
15760 West Power Line Street
Crystal River, FL 34428-6708

B. J. Hickie, Director
Nuclear Plant Operations (NA2C)
FPC, Crystal River Energy Complex
15760 West Power Line Street
Crystal River, FL 34428-6708

David F. Kunsemiller, Director (SA2A)
Nuclear Operations Site Support
FPC, Crystal River Energy Complex
15760 West Power Line Street
Crystal River, FL 34428-6708

R. Alexander Glenn, Corporate Counsel
Florida Power Corporation
MAC - A5A
P. O. Box 14042
St. Petersburg, FL 33733-4042

Attorney General
Department of Legal Affairs
The Capitol
Tallahassee, FL 32304

Bill Passeti
Office of Radiation Control
Dept of Health and Rehab. Serv.
1317 Winewood Boulevard
Tallahassee, FL 32399-0700

Joe Myers, Director
Div. of Emergency Preparedness
Department of Community Affairs
2740 Centerview Drive
Tallahassee, FL 32399-2100

Chairman
Board of County Commissioners
Citrus County
110 N. Apopka Avenue
Inverness, FL 34450-4245

Robert B. Borsum
Framatome Technologies
1700 Rockville Pike, Suite 525
Rockville, MD 20852-1631

FPC

3

Distribution:

K. Landis, RII
 L. Raghavan, NRR
 B. R. Crowley, RII
 G. Hopper, RII
 PUBLIC

NRC Resident Inspector
 U.S. Nuclear Regulatory Comm.
 6745 N. Tallahassee Road
 Crystal River, FL 34428

*FOR PREVIOUS CONCURRENCE SEE ATTACHED

OFFICE							
SIGNATURE							
NAME	LMellen*	KLandis*	JJohnson*	JJaudon*	FHebdon		
DATE	03 / / 97	03 / / 97	03 / / 97	03 / / 97	03 / 3 / 97	03 / / 97	03 / / 97
COPY?	YES NO	YES NO	YES NO	YES NO	YES (NO)	YES NO	YES NO

OFFICIAL RECORD COPY

DOCUMENT NAME: G:\CRYSTAL\LETTERS\96-99.ACK

Florida Power Corporation
Crystal River Energy Complex
Mr. P. M. Beard, Jr. (SA2A)
Sr. VP, Nuclear Operations
ATTN: Mgr., Nuclear Licensing
15760 West Power Line Street
Crystal River, FL 34428-6708

SUBJECT: SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE (SALP)
(NRC INSPECTION REPORT NO. 50-302/96-99)

Dear Mr. Beard:

Thank you for your response of December 20, 1996, to our SALP Report issued on November 25, 1996, concerning the performance of Plant Operations, Maintenance, Engineering and Plant Support activities at your Crystal River facility. We concur with your overall corrective actions which include: a number of organizational and personnel changes, emphasis on the clear communication of expectations and standards with continuing accountability to these high standards, a comprehensive readiness for restart program combined with the commitment represented by a long term shutdown to improve design margin, and the continuing implementation of your Management Corrective Action Plan (MCAP II). We continue to emphasize the need to use adequate performance measurements to assure that your corrective actions are effective in improving overall performance. We will evaluate your corrective actions and resolution of restart issues through a combination of enhanced inspection and under the guidelines established in Manual Chapter 0350 "STAFF GUIDELINES FOR RESTART APPROVAL." Additionally, we will continue to inspect and assess your ongoing efforts to use MCAP II to facilitate improvement in each functional area.

We appreciate your response and attention to the assessment results.

Sincerely,

Luis A. Reyes
Regional Administrator

Docket No. 50-302
License No. DPR-72

OFFICE						
SIGNATURE	<i>J. Melten</i>	<i>J. Melten</i>	<i>J. Johnson</i>	<i>J. Johnson</i>	<i>F. Hebdon</i>	
NAME	J. Melten	J. Melten	J. Johnson	J. Johnson	F. Hebdon	
DATE	02 / 28 / 97	02 / 28 / 97	3 / 3 / 97	02 / 28 / 97	02 / / 97	02 / / 97
COPY?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO	<input type="checkbox"/> YES <input type="checkbox"/> NO

OFFICIAL RECORD COPY

DOCUMENT NAME: G:\CRYSTAL\LETTERS\96-99.ACK