

NOTICE OF VIOLATION

B. F. Goodrich Research Center

License No. 34-02054-07

As a result of the inspection conducted on February 16, 1988, and in accordance with 10 CFR Part 2, Appendix C - General Statement of Policy and Procedure for NRC Enforcement Actions (1987), the following violation was identified:

License Condition No. 14.A. requires each chromatograph detector cell containing nickel-63 shall be tested for leakage and/or contamination at intervals not to exceed six (6) months.


Contrary to the above, each chromatograph detector cell containing nickel-63 has not been tested for leakage every six (6) months as required. Specifically, as of the day of this inspection, Source Serial No. H2930 was tested on April 22, 1986 and February 1, 1984. Source Serial No. G0221 was tested on February 15, 1988, May 5, 1983, June 20, 1978 and September 9, 1977. These frequencies do not satisfy the six month requirement.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each violation: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

MAR 4 1989

Dated _____


D. G. Wiedeman, Chief
Nuclear Materials Safety
Section 1