

ADOLPHO MELICOR, M.D.
MARIA CRUMES, M.D.

South-Allen Radiology

5518 ALLEN ROAD
ALLEN PARK, MI 48101
(313) 388-1930

M. LALA, M.D.
Diplomate-American Board of Radiology
Diplomate American Board of Nuclear Medicine

SA

RADIOLOGY, MAMMOGRAPHY, NUCLEAR MEDICINE, ULTRASOUND, ECHOCARDIOGRAPHY AND VASCULAR STUDIES

May 5, 1997

U.S. Nuclear Regulatory Commission
ATTN: DOCUMENT Control Desk
Washington, D.C. 20555

Dear Sir:

This is in response to your letter of 3/28/97 concerning the inspection conducted on February 25-28, 1997 at Dr. Lala's locations at rochester, Dearborn, Northville and Livonia.


1. A technologist at the 2200 Monroe, Dearborn, MI office did not wear either a whole body film badge or a ring badge when handling radioactive materials.
 - a. The technologist has been re-instructed on the proper wearing of the badges.
 - b. In order to prevent this from happening again a seperate written policy requiring the wearing of badges is being posted at all locations in addition to the safety rules, which is already posted.
 - c. Full compliance was achieved by May 1, 1997.
2. A contamination survey with a GM survey meter was not done at the end of each day at the 2200 Monroe, Dearborn, MI office.
 - a. The technologist has been re-instructed in the proper procedure for conducting all surveys.
 - b. All personnel will receive initial and annual education on the safety rules and required procedures.
 - c. Full compliance was achieved on March 3, 1992.

If there are any questions, please contact me.

Sincerely,

Michael Lala

Michael Lala, M.D.



9705130042 961010
PDR ACRS PDR
3031

30-18558

21-2438-01

10

Leb 7