



Wisconsin Power & Light Company

Investor-owned Energy

COLUMBIA GENERATING STATION

P.O. Box 98

Portage, Wisconsin 53901

April 2, 1987

Control Number 383023

U.S. Nuclear Regulatory Commission
Regional Office Of Inspection & Enforcement
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Log	4/20/87
Remitter	
Check No.	576201
Amount	760
Fee Category	3rd
Type of Fee	2nd
Date Check Rec'd.	4/20/87
Date Completed	4/20/87
By:	CP

Dear Sir or Madam:

I am writing to request that you amend the Application For Byproduct Material License (NRC Form 313 I) for License 48-15518-01 in the following manner: change the paragraph in Item 15 beginning with "The wipe test kit. . ." to read ". . .be evaluated for leakage by the Kewaunee Nuclear Power Plant of the Wisconsin Public Service Corporation."

As requested by your office, below is the procedure used in performing a leak test of our Ohmart sealed sources.

Leak Test Kit

The kit consists of a wiping swab (a cotton tipped wooden stick) and a numbered, ziplock sealed, plastic bag. One kit is used for each source to be tested. When taking leak tests, the kits are accompanied by a small plastic bottle of alcohol detergent solution.

Leak Test Procedure

Other than leak tests performed by Omart Corp. field service representatives, all leak tests are to be performed by the Radiation Safety Officer on a 3 year interval.

1. Grasp a swab by it's wooden shaft and dip the cotton end into the alcohol detergent solution.
2. Wipe the external surface of the source holder with the cotton tipped end. Wipe all seams and around rotor shafts since these areas are most likely to be contaminated if the source leaks.

B801250181 B70727
REG3 LIC30
48-15515-01 PDR

Und - 83327 - [signature]


Wisconsin's heartland . . . on the grow.



3. After taking the leak test, place the swab in a plastic bag with the cotton end at the bottom of the bag and seal it shut.
4. Record the number of the kit on the corresponding leak test report form, which contains the source information (i.e. serial number, location, activity, isotope, etc.).
5. After all tests have been performed, send the leak test kits and report forms to the Kewaunee Nuclear Power Plant.

If you need any further information concerning procedures or control measures use at the Columbia Generating Station, please let me know.

Sincerely,


Greg Lawrence
Radiation Safety Officer

Enclosure:
WPL Chk #576201



Wisconsin Power & Light Company
Investor-owned Energy

#76201

12.2
750

MADISON, WI 53701-0192

No. 576201

DATE
MARCH 27, 1987

CHECK AMOUNT
*****60 DOLLARS

.00 CENTS

\$60.00

PAY TO THE ORDER OF

VOID AFTER 90 DAYS
VOUCHER CHECK

UNITED STATES REGULATORY
COMMISSION
REGION III
799 ROOSEVELT RD
GLEN ELLYN IL 60137

Edm Bleaser
AUTHORIZED SIGNATURE

FIRST WISCONSIN NATIONAL BANK, MILWAUKEE, WI

⑈ 576201 ⑈ ⑆075000022⑆ ⑆⑆⑆5⑆7⑈643⑈

DETACH THIS STATEMENT BEFORE DEPOSITING CHECK

H

DATE
03/27/87

VENDOR NO.
0004193-002

CHECK NO.
576201

INVOICE NUMBER	INVOICE DATE	DEDUCTION AMOUNT	DED CODE	GROSS AMOUNT	DISCOUNT	NET AMOUNT
GL0324	03 24			60.00		60.00

Amend byproduct material license 48-15518-01 for leak test analysis by Kewaunee Nuclear Power Plant rather than the Ohmart Corp. (include on check - control number 383023)

*****60.00

ATTACHED CHECK IS PAYMENT FOR ITEMS LISTED.
IF NOT CORRECT, RETURN CHECK WITH EXPLANATION.

WISCONSIN POWER AND LIGHT COMPANY, P.O. BOX 192, MADISON WI 53701-0192

DEDUCTION CODES
1-FREIGHT ELIMINATED
2-TAX ELIMINATED
3-SEE CORRECTION MEMORANDUM

this number was not included on the check
when I received it so I wrote it on by
hand before sending it to your Glen Ellyn
office.



Wisconsin Power & Light Company

Investor-owned Energy

COLUMBIA GENERATING STATION

P.O. Box 98

Portage, Wisconsin 53901

Log	4/20/87
Remitter	576201
Check No.	360
Amount	30
Fee Category	and
Type of Fee	
Date Check Rec'd.	4/20/87
Date Completed	8/1
By:	

April 2, 1987

Control Number 383023

U.S. Nuclear Regulatory Commission
Regional Office Of Inspection & Enforcement
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Sir or Madam:

I am writing to request that you amend the Application For Byproduct Material License (NRC Form 313 I) for License 48-15518-01 in the following manner: change the paragraph in Item 15 beginning with "The wipe test kit. . ." to read ". . .be evaluated for leakage by the Kewaunee Nuclear Power Plant of the Wisconsin Public Service Corporation."

As requested by your office, below is the procedure used in performing a leak test of our Ohmart sealed sources.

Leak Test Kit

The kit consists of a wiping swab (a cotton tipped wooden stick) and a numbered, ziplock sealed, plastic bag. One kit is used for each source to be tested. When taking leak tests, the kits are accompanied by a small plastic bottle of alcohol detergent solution.

Leak Test Procedure

Other than leak tests performed by Omart Corp. field service representatives, all leak tests are to be performed by the Radiation Safety Officer on a 3 year interval.

1. Grasp a swab by it's wooden shaft and dip the cotton end into the alcohol detergent solution.
2. Wipe the external surface of the source holder with the cotton tipped end. Wipe all seams and around rotor shafts since these areas are most likely to be contaminated if the source leaks.

RECEIVED

APR 6 1987

REGION III



APR 6 1987

CONTROL NO. 83327


Wisconsin's heartland on the grow.

8801250181 2 pp.

3. After taking the leak test, place the swab in a plastic bag with the cotton end at the bottom of the bag and seal it shut.
4. Record the number of the kit on the corresponding leak test report form, which contains the source information (i.e. serial number, location, activity, isotope, etc.).
5. After all tests have been performed, send the leak test kits and report forms to the Kewaunee Nuclear Power Plant.

If you need any further information concerning procedures or control measures use at the Columbia Generating Station, please let me know.

Sincerely,


Greg Lawrence
Radiation Safety Officer

Enclosure:
WPL Chk #576201