

ENCLOSURE 1

Nebraska Public Power District  
Cooper Nuclear Station  
Docket No. 50-298

NOTICE OF DEVIATION

Based on the results of an NRC inspection conducted during the period August 28-30, 1978, it appears that one of your activities was not conducted in accordance with an industry approved code as indicated below.

Section 14-1.2 of NFPA 80-1977, "Fire Doors and Windows," requires, in part, that all fire doors be operable at all times and that they shall be kept closed and latched or arranged for automatic closing.

Contrary to this requirement, it was noted on August 28, 1978 that the fire door in the reactor building, 903 level leading to the southwest quadrant, was blocked open by a hose, rendering this door inoperable. This condition was noted after normal working hours, and no fire watch was present.

This is a deviation.

781106 0053