



Commonwealth Edison  
One First National Plaza, Chicago, Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690

*Central Mail &  
Files Unit*

June 7, 1976

Mr. James G. Keppler, Director  
Directorate of Inspection and  
Enforcement - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Subject: Dresden Station Unit 1  
IE Inspection Report No. 50-10/76-03  
NRC Docket No. 50-10

Reference (a): J. M. Allan's letter to Byron Lee, Jr.,  
dated April 22, 1976

Dear Mr. Keppler:

The following is a supplemental reply to the subject IE  
inspection report requested by reference (a).

#### Decontamination/First Aid Facilities

It is important to clarify that our plans are to provide a  
permanent area for first aid supplies near the decontamination  
facility. Until this permanent facility is available, a standard  
Commonwealth Edison Company first aid kit will be maintained in the  
area of the present decontamination facility. In our judgement,  
these provisions will meet the GSEP requirement, although they are  
not optimum.

#### Emergency Plan Implementing Procedures

To clarify our intent relative to supplemental emergency  
procedures, it is our intent to include references only in the  
Emergency Plan Implementing Procedures for subjects covered by other  
Dresden Station Procedures. Dresden Station Procedures are con-  
trolled and copies are maintained in numerous locations including  
the Control Room, the Shift Engineer's Office, the Assistant  
Superintendent's Office, and the Technical Staff Supervisor's  
Office. Copies of these procedures are also sent to the Production

8010270581

Q

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES

Commonwealth Edison

Mr. James G. Keppler

- 2 -

June 7, 1976


System Analysis Department and the NRC Region III office. In these locations, they are readily available for reference in the event of an emergency and they are available for your review.

We agree that during an emergency, these referenced procedures must be available without searching. Incorporating the appropriate reference in the Supplemental Emergency Procedures ensures that the applicable procedure will be identified quickly. The numerous locations and organization of these procedures ensures they will be quickly implemented after identification.

We would like to take this opportunity to comment on paragraph 7.a.2, page 11 of the subject inspection report. The third sentence should read "New Rad-Men receive a 10-hour first aid training course."

Please contact this office if you have any additional questions on this matter.

Very truly yours,



R. L. Bolger  
Assistant Vice President