


70-754
GENERAL ELECTRIC **RETURN TO** ^{P-137}
~~396-SS~~

NUCLEAR ENERGY BUSINESS OPERATIONS
GENERAL ELECTRIC COMPANY • VALLECITOS NUCLEAR CENTER • PLEASANTON, CALIFORNIA 94566

February 29, 1988



L. C. Rouse, Chief
Fuel Cycle Safety Branch
Office of Nuclear Material Safety & Safeguards
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555


References: 1. License SNM-960, Docket 70-754;
2. Vallecitos Nuclear Center Radiological Contingency Plan;
November, 1982; as revised.

Dear Mr. Rouse:

Enclosed are revised pages to the Vallecitos Nuclear Center Radiological Contingency Plan. Changes are indicated by vertical lines in the right-hand margin. Also enclosed is a list summarizing the changes.

As these changes do not decrease the effectiveness of the plan, they are being reported pursuant to 10CFR70.32(1).

Sincerely,


G. E. Cunningham
Senior Licensing Engineer
(415) 862-4330

/ca

Enclosures



8803300476 880229
PDR ADOCK 07000754
C PDR

FEE NOT REQUIRED

Does Not Decrease
Effectiveness of the Plan

29115

22-708 OF 180754



DOCKET NO. 70-754
CONTROL NO. 29115
DATE OF DOC. 2/29/88
DATE RCVD. 3/9/88
FCUF ✓ PDR ✓
FCAF ✓ LPDR ✓
I & E REF. ✓
SAFEGUARDS ✓
OTHER ✓
FCTC ✓
DATE 3/9/88 INITIAL Sac



GENERAL ELECTRIC

<u>Change No.</u>	<u>Page No.</u>	<u>Change</u>
1	vii	Deleted reference to the Specialist, Safeguards, as changes in site safeguards and security requirements have eliminated the need to retain him on emergency teams.
2	1-16	Figure 1.2-8 changed to show that facility shops have been moved from Building 104 to Building 106. Building 104 currently is used only for storage.
3	1-21	Paragraph describing the analytical laboratory was moved from Section 1.2.7.2.2. It is located on the first floor of Building 102, not in the basement.
4	1-21	See Change No. 2.
5	1-22	Indicates the current condition and use of Buildings 400 and 401.
6	1-25	See Change No. 2.
7	1-26	Updates Building 106 use information to indicate that all facilities shops have been moved from Building 104 to Building 106.
8	1-28	Updates Building 400 description to indicate complete decontamination, disposal of equipment, and current use.
9	1-32	Corrects "Sampling Flow Rate" (column 7) for Stack No. 26 from 0.7 to 2.0 ft ³ /min.
10	2-3	Changed "Commander" to "Coordinator", which is the title currently used.
11	3-5	Changed "500 milliRem" to "50 milliRem" to make consistent with Par. 3.2.1, Item No. 1, p. 3-3.
12	3-6	Changed "1 Rem" to "0.5 Rem" to make consistent with Par. 3.2.2, Item No. 1, p. 3-3.
13	4-1	Deleted "...which is itself a production entity", which is useless and incorrect information.
14	4-1	Updated organizational relationships and names.
15	4-3	Wording changed to indicate the EOC is not expected to be in command until he becomes aware of the emergency.

GENERAL ELECTRIC

<u>Change No.</u>	<u>Page No.</u>	<u>Change</u>
16	4-3	Eliminated the Area Manager as the Manager-IP's alternate for single facility emergencies.
17	4-4	Figure 4-4 changed to indicate the Specialist, Safeguards, has been relieved of his emergency response duties and that the Area Manager is no longer the Manager-IP's alternate for single facility emergencies.
18	4-5	Changed to state that Manager-IP's alternate for all emergencies is a member of his staff determined from a succession list of three staff members. The list of the three position titles has been deleted. An up-to-date list is maintained in the implementing procedures.
19	4-7	Emergency response responsibilities of the Senior Licensing Engineer were not necessary for the implementation of the plan and have been deleted. These responsibilities are described in the Site Emergency Procedures.
20	4-8	Par. 4.2.2.5, Item No. 1 deleted (see Change No. 16) and items renumbered. New Item No. 3 changed to indicate all Area Managers do not "appoint" a Building Emergency Team (BET).
21	4-8	A "site fire team" appointed by the Manager, IP, has replaced the BET firemen appointed by the Area Managers. This team includes the Site Fire Marshal and will respond to fires anywhere on site. Team membership is sufficient to permit simultaneously response to fire alarms from different facilities.
22	4-11	Clarifies the responsibility for requesting ambulance service.
23	5-8	See Change No. 22.
24	6-3	Corrects statement about maintenance and calibration of monitoring equipment by eliminating the reference to an "automated" plan which is no longer used.
25	6-7	The position title, "Specialist, Environmental Protection", has been eliminated. The duties are performed by the Specialist, Facilities Protection.

GENERAL ELECTRIC

<u>Change No.</u>	<u>Page No.</u>	<u>Change</u>
26	7-1	Vallecitos Safety Standard 1.4 was found to be superfluous and was eliminated. Responsibility for the emergency procedures is assigned to the Manager, Nuclear Safety.
27	7-1	Changed to clarify that changes to the Site Emergency Procedures are made in accordance with the referenced NS Administrative Procedure. As stated in the first paragraph of Sec. 7.1, the Manager, Nuclear Safety, is responsible for ensuring the review of procedures that might be considered as implementing procedures.
28	7-1	Added "first aid" as another exception to the classes provided by Nuclear Safety. This training is provided by an American Red Cross instructor.
29	7-3	Changed to reflect that a site fire team has replaced the BET firemen. See Change No. 21.
30	7-3	The first aid course does not cover the subject of emergency dose limits which is addressed in the RSVNC course and general emergency support training. The course name has been changed accordingly.
31	7-5	Changed to eliminate (1) the ambiguous term "each primary area" and (2) the need to hold annual fire drills in deactivated areas.
32	9-1	Added a sentence to clarify the extent of the BEC's authority.