



UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

06 NOV 1980

License No. 35-16164-01

RECEIVED DISTRIBUTION
SERVICES UNIT

1980 DEC 8 PM 2 23

Peabody Pipeline Testing Company
Attn: Coleman McDonough, Vice President
5433 South 101st Ave.
Tulsa, Oklahoma 74145

Gentlemen:

This refers to the investigation conducted by Mr. N. M. Shopenn of this office on October 14-15, 1980, of the activities authorized by NRC Byproduct Material License No. 35-16164-01 and to the discussion of our findings held by Mr. Shopenn with Harold D. Adkison, General Manager, Terry Baker, RSO and Ray Terril, Assistant RSO on October 15, 1980.

The investigation was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The investigation consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements and observations by the inspector.

No items of noncompliance with NRC requirements were found during the investigation.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed investigation report will be placed in the NRC's Public Document Room. If the report contains any information that you believe to be proprietary, it is necessary that you make a written application to this office, within twenty (20) days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons it is claimed that the information is proprietary. It should be prepared so that any proprietary information identified is contained in a separate part of the document, since the application, excluding this separate part, will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

0012240

110

Central
Files

Peabody Pipeline Testing Company

2

Should you have any questions concerning this investigation, please let me know.

Sincerely,



Glen D. Brown, Chief
Fuel Facility and Material
Safety Branch

Enclosure:

IE Inspection Report No. 35-16164-01