

MATERIALS LICENSE

ORC

Pursuant to the Atomic Energy Act of 1954, as amended, the Energy Reorganization Act of 1974 (Public Law 93-438), and Title 10, Code of Federal Regulations, Chapter I, Parts 30, 31, 32, 33, 34, 35, 36, 39, 40, and 70, and in reliance on statements and representations heretofore made by the licensee, a license is hereby issued authorizing the licensee to receive, acquire, possess, and transfer byproduct, source, and special nuclear material designated below; to use such material for the purpose(s) and at the place(s) designated below; to deliver or transfer such material to persons authorized to receive it in accordance with the regulations of the applicable Part(s). This license shall be deemed to contain the conditions specified in Section 183 of the Atomic Energy Act of 1954, as amended, and is subject to all applicable rules, regulations, and orders of the Nuclear Regulatory Commission now or hereafter in effect and to any conditions specified below.

Licensee

1. Healthsouth Diagnostic Centers
of Anchorage, LTD.

2. 4003 Lake Otis Parkway, #101
Anchorage, Alaska 99508

In accordance with letter dated

April 8, 1997

3. License Number 50-23214-01 is amended in
its entirety to read as follows:

4. Expiration Date September 30, 2004

5. Docket or
Reference No. 030-20372

6. Byproduct, Source, and/or
Special Nuclear Material

7. Chemical and/or Physical
Form

8. Maximum Amount that Licensee
May Possess at Any One Time
Under This License

A. Any byproduct
material identified
in 10 CFR 35.100

B. Any byproduct
material identified
in 10 CFR 35.200

C. Iodine-131

D. Strontium-89

A. Any
radiopharmaceutical
identified in
10 CFR 35.100

B. Any
radiopharmaceutical
identified in
10 CFR 35.200

C. Iodide

D. Chloride

A. As needed

B. As needed

C. 30 millicuries per
dose; not to exceed
70 millicuries
total

D. 4 millicuries per
dose; not to exceed
8 millicuries total

9. Authorized use

- A. Medical use described in 10 CFR 35.100.
B. Medical use described in 10 CFR 35.200.
C. Diagnosis and treatment of hyperthyroidism and cardiac dysfunction.
D. Treatment of pain due to metastatic bone carcinoma.

140042

XA 7/21/97

9707070195

18pp

o/h
ML40

MATERIALS LICENSE
SUPPLEMENTARY SHEET

License Number
50-23214-01

Docket or Reference Number
030-20372

Amendment No. 10

CONDITIONS

10. Licensed material shall be used only at the licensee's facilities located at 4003 Lake Otis Parkway, #101, Anchorage, Alaska.
11. The Radiation Safety Officer for this license is John J. McCormick, M.D.
12. Licensed material listed in Item 6 above is only authorized for use by, or under the supervision of, the following individuals for the materials and uses indicated:

Authorized Users

Material and Use

Harold F. Cable, M.D.

10 CFR 35.100, 35.200 and Iodine-131

George H. Ladyman, M.D.

10 CFR 35.100, 35.200, Iodine-131,
and Strontium-89

James L. Faries, M.D.

10 CFR 35.100, 35.200, Iodine-131,
and Strontium-89

John J. McCormick, M.D.

10 CFR 35.100, 35.200 and Iodine-131

13. The licensee is authorized to transport licensed material only in accordance with the provisions of 10 CFR Part 71, "Packaging and Transportation of Radioactive Material."

MATERIALS LICENSE
SUPPLEMENTARY SHEET

License Number
50-23214-01

Docket or Reference Number
030-20372

Amendment No. 10

14. Except as specifically provided otherwise in this license, the licensee shall conduct its program in accordance with the statements, representations, and procedures contained in the documents, including any enclosures, listed below, except for minor changes in the medical use radiation safety procedures as provided in 10 CFR 35.31. The Nuclear Regulatory Commission's regulations shall govern unless the statements, representations, and procedures in the licensee's application and correspondence are more restrictive than the regulations.

- A. Letter dated July 29, 1994
- B. Letter dated August 11, 1994
- C. Application dated August 1, 1994
- D. Letter dated August 15, 1994
- E. Letter dated April 8, 1997
- F. Letter received May 15, 1997
- G. Letter dated May 21, 1997

FOR THE U.S. NUCLEAR REGULATORY COMMISSION

Date JUN 27 1997

By Beth A. Prange
Materials Branch
Region IV, WCFO
Walnut Creek, California 94596

✓ MS10

(FOR LFMS USE)
INFORMATION FROM LTS

BETWEEN:

License Fee Management Branch, ARM
and
Regional Licensing Sections

Program Code: 02200
Status Code: 0
Fee Category: 7C
Exp. Date: 20040930
Fee Comments: 1
Decom Fin Assur Req'd: N

1997 APR 17 PM 12:48

LICENSE FEE TRANSMITTAL

A. REGION IV WCFO

1. APPLICATION ATTACHED

Applicant/Licensee: ANCHORAGE DIAGNOSTIC IMAGING CTR.
Received Date: 970416
Docket No.: 3020372
Control No.: 572487
License No.: 50-23214-01
Action Type: Amendment

2. FEE ATTACHED
Amount: \$ 440.00
Check No.: 4174

3. COMMENTS

Signed
Date

4-16-97

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered ✓)

1. Fee Category and Amount: 7C \$440

2. Correct Fee Paid. Application may be processed for:

Amendment
Renewal
License

3. OTHER

Signed
Date

4/17/97

Log	<u>Apr 2 WCFO</u>
Remitter	
Check No.	<u>4174</u>
Amount	<u>\$440</u>
Fee Category	<u>7C</u>
Type of Fee	<u>Amend</u>
Date Check Rec'd.	
Date Completed	<u>4/17/97</u>
By:	<u>Rem</u>



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV

Walnut Creek Field Office
1450 Maria Lane
Walnut Creek, California 94596-5368

JUN 27 1997

Healthsouth Diagnostic Centers
of Anchorage, LTD.
ATTN: John J. McCormick
Radiation Safety Officer
4003 Lake Otis Parkway, #101
Anchorage, Alaska 99508

SUBJECT: LICENSE AMENDMENT AND NOTICE OF VIOLATION

Please find enclosed License No. 50-23214-01. You should review this license carefully and be sure that you understand all conditions.

Please note that as part of this amendment, in accordance with 10 CFR 30.36, effective February 15, 1996, the expiration date of your license has been extended by a period of five years. Your new expiration date is stated in Item 4 of the license. If you have any questions, you may contact the reviewer who signed your license at (510) 975-0250.

NRC expects licensees to conduct their programs with meticulous attention to detail and a high standard of compliance. Because of the serious consequences to employees and the public which can result from failure to comply with NRC requirements, you must conduct your program involving radioactive materials in accordance with the conditions of your NRC license, representations made in your license application, and NRC regulations. In particular, note that you must:

1. Operate in accordance with NRC regulations 10 CFR Part 19, "Notices, Instructions and Reports to Workers: Inspection and Investigations," 10 CFR Part 20, "Standards for Protection Against Radiation," and other applicable regulations.
2. Possess radioactive material only in the quantity and form indicated in your license.
3. Use radioactive material only for the purpose(s) indicated in your license.
4. Notify NRC in writing of any change in mailing address (no fee required if the location of radioactive material remains the same).
5. Request and obtain written NRC consent before transferring your license or any right thereunder, either voluntarily or involuntarily, directly or indirectly, through transfer of control of your license to any person or entity. A transfer of control of your license includes not only a total change of ownership, but also a change in the controlling interest in your company whether it is a corporation, partnership, or other entity. In addition, appropriate license amendments must be requested and obtained for any other planned changes in your facility or program that are contrary to your license or contrary to representations made in your license application, as

well as supplemental correspondence thereto, which are incorporated into your license. A license fee may be charged for the amendments if you are not in a fee-exempt category.

6. Maintain in a single document, decommissioning records that have been certified for completeness and accuracy listing all the following items applicable to the license:
 - Onsite areas designated or formerly designated as restricted areas as defined in 10 CFR 20.3(a)(14) or 20.1003.
 - Onsite areas, other than restricted areas, where radioactive materials in quantities greater than amounts listed in Appendix C to 10 CFR 20.1001-20.2401 have been used, possessed, or stored.
 - Onsite areas, other than restricted areas, where spills or other unusual occurrences involving the spread of contamination in and around the facility, equipment, or site have occurred that required reporting pursuant to 10 CFR 30.50(b)(1) or (b)(4), including areas where subsequent cleanup procedures have removed the contamination.
 - Specific locations and radionuclide contents of previous and current burial areas within the site, excluding radioactive material with half-lives of 10 days or less, depleted uranium used only for shielding or as penetrators in unused munitions, or sealed sources authorized for use at temporary job sites.
 - Location and description of all contaminated equipment involved in licensed operations that is to remain onsite after license termination.
7. Submit a complete renewal application with proper fee, or termination request at least 30 days before the expiration date on your license. You will receive a reminder notice approximately 90 days before the expiration date. Possession of radioactive material after your license expires is a violation of NRC regulations.
8. Request termination of your license if you plan to permanently discontinue activities involving radioactive material.

You will be periodically inspected by NRC. Failure to conduct your program in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in enforcement action against you. This could include issuance of a notice of violation; imposition of a civil penalty; or an order suspending, modifying, or revoking your license as specified in the "General Statement of Policy and Procedure for NRC Enforcement Actions" (Enforcement Policy), 60 FR 34381, June 30, 1995.

Heathsouth Diagnostic Centers
of Anchorage, LTD.


-3-

This letter also responds to your letter dated April 8, 1997, to your letter received May 15, 1997, and to your letter dated May 21, 1997, wherein the NRC was informed of the direct transfer of License 50-23214-01, effective February 3, 1997. We find that the information supplied by Healthsouth Diagnostic Centers of Anchorage, LTD. was sufficient to make a finding that the transfer was in accordance with the Atomic Energy Act of 1954, as amended. However, the license transfer should not have taken place until the NRC had given its written consent, as required by 10 CFR 30.34(b).

Therefore, enclosed with this letter is a Notice of Violation (Notice) based on failure to obtain prior written consent from NRC to this license transfer. Your actions in response to this matter were considered appropriate and we are not requiring you to respond to the Notice.

Should you have any questions regarding this matter, feel free to contact Beth Prange of my staff at 510-975-0250.

Sincerely,



Frank A. Wenslawski, Chief
Materials Branch

Docket: 030-20372
License: 50-23214-01
Control: 572487

Enclosures: As stated

cc w/enclosures:
State of Alaska

Heathsouth Diagnostic Centers
of Anchorage, LTD.

-4-

bcc:
E-Mail report to Document Control Desk (DOCDESK)

bcc to DCD (IE-07)
RIV Regional Administrator
RScarano
LLHowell
DBSpitzberg
FAWenslawski
Docket File
WCFO Inspection File
NMI&FC/DB
LFARB, T-9 E10
MIS System
RIV Nuclear Materials File -5th Floor

DOCUMENT NAME: G:\BETH\572487

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:MB	RIV:MB	C	RIV:MB	RIV:MB	N		
K Prendergast	BPrange	BAP	JMontgomery	FWenslawski	gan		
197	6/23/97	1/97	6/27/97				

OFFICIAL RECORD COPY

ENCLOSURE

NOTICE OF VIOLATION

Healthsouth Diagnostic Centers
of Anchorage, LTD.
Anchorage, Alaska

Docket No. 030-20372
License No. 50-23214-01

During the NRC's review of the licensee's submit. dated April 8, 1997, which requested a name change on License 50-23214-01, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement" NUREG-1600, the violation is listed below:

10 CFR 30.34(b) states, in part, that no license issued or granted pursuant to the regulations in this part and Parts 31 through 36, and 39, nor any right under a license shall be transferred, assigned or in any manner disposed of either voluntarily or involuntarily, directly or indirectly, through transfer of control of any license to any person, unless the Commission shall, after securing full information, find that the transfer is in accordance with the provisions of the Atomic Energy Act of 1954, as amended, and shall give its consent in writing.

Contrary to the above, effective February 3, 1997, a direct transfer of License No. 50-23214-01 occurred. This direct transfer consisted of a purchase of the assets and liabilities of Anchorage Diagnostic Imaging Center, Inc. by Healthsouth Diagnostic Center, Inc. As dictated in the agreement, a limited partnership was formed, Healthsouth Diagnostic Centers of Anchorage, Ltd. This joint venture has full responsibility for the NRC license. This direct license transfer was made without first providing NRC an opportunity to determine whether the transfer was in accordance with the provisions of the Act and to consent in writing to the transfer.

This is a Severity Level IV violation (Supplement VI).

The NRC has concluded that information regarding the reason for the violation, the corrective actions taken and planned to correct the violation and prevent recurrence and the date when full compliance was achieved is already adequately addressed on the docket. However, you are required to submit a written statement or explanation pursuant to 10 CFR 2.201 if the description therein does not accurately reflect your corrective actions or your position. In that case, or if you choose to respond, clearly mark your response as a "Reply to a Notice of Violation," and send it to the U. S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington D.C. 20555 with a copy to the Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, within 30 days of the date of the letter transmitting this Notice of Violation.

If personal privacy or proprietary information is necessary to provide an acceptable response, then please provide a bracketed copy of your response that identifies the information that should be protected and a redacted copy of your response that deletes

such information. If you request withholding of such material, you must specifically identify the portions of your response that you seek to have withheld and provide in detail the bases for your claim of withholding (e.g. explain why the disclosure of information will create an unwarranted invasion of personal privacy or provide the information required by 10 CFR 2.790(b) to support a request for withholding confidential commercial or financial information). If safeguards information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21.

Dated at Walnut Creek, California
this ^{27th} day of *June* 1997.

HEALTHSOUTH Diagnostic Centers of Anchorage, LTD.

4003 Lake Otis Parkway, Suite 101 * Anchorage, Alaska 99508-5270

Clinic: 907-563-3493 Fax: 907-561-2596 Business Office: 907-562-6655 Fax: 907-563-6195

97 MAY 23 AM 10:09

5-21-97

Nuclear Regulatory Commission
Region IV, Walnut Creek Field Office
1450 Maria Lane
Walnut Creek, CA 94596-5368
Attention: Beth A. Prange

RE: Healthsouth Diagnostic Centers of Anchorage, Ltd.
Control # - 572487


Dear Ms. Prange,

This letter is in response to your FAX dated May 16, 1997 regarding our change in ownership.


1. All records referenced in 10 CFR 30.35(g) were transferred to the new owner, Healthsouth Diagnostic Centers of Anchorage, Ltd.
2. The new owner, Healthsouth Diagnostic Centers of Anchorage, Ltd., accepts full liability for the site listed on our Byproduct Radioactive Materials License.

If any additional information is needed, please do not hesitate to contact me at (907) - 563-3493.

Sincerely,



John J. McCormick, M.D.
Radiation Safety Officer



Theresa M. Harris, Administrator
Healthsouth Diagnostic Centers

5/16/97

TELECOPIER TRANSMITTAL

TIME

4:05p.m.

WARNING: Most facsimile machines produce copies on thermal paper. The image produced is highly unstable and will deteriorate significantly in a few years. Reproduce copies onto plain paper prior to filing as a record.

TO

NAME

Dr. John Mc Cormick

TELEPHONE

(907) 563-3493

NAME AND LOCATION OF COMPANY (If other than NRC)

Healthsouth Diagnostic Centers of Anchorage, LTD.

TELECOPY NUMBER

(907) 561-2596

VERIFICATION NUMBER

FROM

NAME

Beth Prange

TELEPHONE

(510) 975-0250

MAIL STOP

RIV; WCFO

TELECOPY DATA

NUMBER OF PAGES

THIS PAGE + 0 PAGES = 1 TOTAL

PRIORITY

IMMEDIATE

OTHER
(Specify)

SPECIAL INSTRUCTIONS

with regard to your recent letter discussing ownership change, I still need two items:

- 1.) Confirmation that all records referenced in 10 CFR 30.35(g) - spills, waste disposals, as-built drawing of the facility, ventilation ducts, pipelines, etc. were transferred to the new owner.
 - 2.) A confirmation that the new owner accepts full liability for the site.
- Thanks.

PROBLEMS

If any problems occur or if you do not receive all the pages, call:

TELEPHONE

PROCESSED BY (INITIALS)

DISPOSITION OF ORIGINAL

After telecopy has been sent, process the original as requested below. (If none are checked, the original will be discarded.)

RETURN TO SENDER

CALL AND SENDER WILL PICK UP

DISCARD

VERIFIED BY (INITIALS)

HEALTHSOUTH Diagnostic Centers of Anchorage, LTD.

4003 Lake Otis Parkway, Suite 101 * Anchorage, Alaska 99508-5270

Clinic: 907-563-3493 Fax: 907-561-2596 Business Office: 907-562-6655 Fax: 907-563-6195

Nuclear Regulatory Commission
Region IV, Walnut Creek Field Office
1450 Maria Lane
Walnut Creek, CA 94596-5368
Attention: Beth A. Prange

RE: Control number: 572487
Transfer of Ownership

Dear Ms. Prange:

This letter is to notify the NRC of the transfer of ownership of Anchorage Diagnostic Imaging Center to Healthsouth Diagnostic Centers of Anchorage, Ltd. The following paragraphs correspond to the notice requirement outlined in NRC Information Notice 89-25, Rev. 1: "Unauthorized Transfer of Ownership or Control of Licensed Activities." The answers to the questions in Attachment 1 of the above information notice are listed below.

1. The new name of the licensed organization is HEALTHSOUTH DIAGNOSTIC CENTERS OF ANCHORAGE, LTD.
2. The new licensee's contact person still remains John McCormick, M.D., Radiation Safety Officer. Dr. McCormick was RSO for Anchorage Diagnostic Imaging Center. The telephone number remains (907) 563-3493.
3. The management of the organization has changed with the sale of Anchorage Diagnostic Imaging Center. The president of the new organization is Russell Maddox. As stated earlier the Radiation Safety Officer, John McCormick, M.D. will remain in that capacity. As it currently stands, all authorized users on the license are current and are to remain on the license. Any changes to the above as it concerns the RSO or authorized users will result in an amendment or notification to the NRC, as appropriate.
4. The transferor will remain in non-licensed business without the license.
5. On February 3 and backdated to February 1, 1997, Healthsouth Diagnostic Center, Inc. purchased all assets and liabilities of Anchorage Diagnostic Imaging Center, Inc. No actual stock transfer was accomplished at this time. As dictated in the agreement, a limited partnership was formed, Healthsouth Diagnostic Centers of Anchorage, Ltd. The principals of Anchorage Diagnostic Imaging Center, Inc., George H. Ladyman, M.D., James L. Faries, M.D., and John J. McCormick, M.D. became limited partners in Healthsouth Diagnostic Centers of Anchorage, Ltd. The joint venture is 80% Healthsouth and 20% Drs. Ladyman, Faries, and McCormick. Drs. Ladyman, Faries, and McCormick retain full responsibility for professional management of the facility, professional radiology services, and the continued management of the NRC license and all radioactive materials in our possession.
6. The new organization (additional owners) will be the only change to the license. The location, facility, equipment, and procedures will remain the same.

FORMERLY: "Anchorage Diagnostic Imaging Center, Inc." & "Chugach Outpatient X-Ray Services"

572487

7. There will be no changes in the use, possession, location, or storage of licensed materials from that previously submitted with our license application.
8. There will be no changes in location, facilities, equipment, procedures, or personnel with the transfer of ownership that would require a license amendment.
9. All records (e.g. calibrations, leak tests, surveys, inventories, and accountability requirements) were current at the time of transfer. This includes all records required by our license conditions and 10 CFR.
10. The specific license for Anchorage Diagnostic Imaging Center does not meet the requirements of 10 CFR 30.35 for submitting a decommissioning funding plan.
11. There was no known contamination present at the time of the transfer of ownership.
12. There are no decontamination plans which would require financial assurance arrangements of the transferee.
13. The transferee, Healthsouth Diagnostic Centers of Anchorage, Ltd. , agrees to abide by all the commitments and representations previously made to the NRC by Anchorage Diagnostic Imaging Center. This would include any open inspection items. The last inspection of Anchorage Diagnostic Imaging Center was on August 29 and 30, 1995. The two violations have been addressed.
14. Anchorage Diagnostic Imaging Center and Healthsouth Diagnostic Centers agree to the change in ownership and control of the licensed material and activity and the conditions of transfer. Healthsouth Diagnostic Centers has been made aware of any open inspection items, as alluded to in the response to Question 13 above.
- 15.. Healthsouth Diagnostic Centers, as transferee commits to abide by all constraints, conditions, requirements, representations, and commitments identified in the existing license.

Healthsouth Diagnostic Centers of Anchorage, Ltd.

By: 

Anchorage Diagnostic Imaging Center

By: 



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV

Walnut Creek Field Office
1450 Maria Lane
Walnut Creek, California 94596-5368

APR 16 1997

Anchorage Diagnostic Imaging Center, Inc.
ATTN: Kay Ladyman
Administrator
4003 Lake Otis Parkway, Suite 101
Anchorage, Alaska 99508-5211

SUBJECT: ACKNOWLEDGMENT OF REQUEST FOR LICENSING ACTION

REFERENCE: Letter dated April 8, 1997

We have completed the administrative review and initial processing of your application. During the initial processing, some deficiencies were identified. Please provide us with answers to the questions in Attachment 1 to NRC Information Notice 89-25, Rev. 1 (copy enclosed). This information should be provided within 30 days from the date of this letter, so that your request can be forwarded for technical review. Please note that the technical review may identify additional omissions in the submitted information or technical issues that require additional information.

Amendment actions are normally processed within 90 days, unless the technical review identifies:

- Major technical deficiencies
- Policy issues that require input and coordination with other NRC Regional offices, Agreement State offices, or NRC's Office of Nuclear Materials and Safeguards

A copy of your correspondence has been forwarded to our License Fee and Accounts Receivable Branch, Office of the Controller, who will contact you separately if the appropriate license fee has not been submitted for your request, or for billing if your request is subject to full cost recovery.

Any correspondence about this application should reference the Control number listed below.

Sincerely,

Beth A. Prange

Beth A. Prange
Sr. Health Physicist (Licensing)
Materials Branch

Docket No. 030-20372
License No. 50-23214-01
Control No. 572487

Enclosure: As stated

ORC

Anchorage Diagnostic
Imaging Center, Inc.

- 2 -

bcc:
Docket File

G:\572487.akl

To receive a copy of this document, indicate in the box "C" - Copy without
attachment/enclosure "E" - Copy with attachment/enclosure "N" - No Copy

OFFICE	RIV:WCFO:NMLB	N		N
NAME	J. Garcia <i>JG</i>	B. Prange <i>BAP</i>		
DATE	4/16/97 <i>JG</i>	4/16/97		

DATE 5/2/97

TELEPHONE OR VERBAL CONVERSATION
RECORD

TIME

☐ INCOMING CALL ☒ OUTGOING CALL ☐ VISIT

PERSON CALLING:

Jim Montgomery

OFFICE/ADDRESS:

PHONE NUMBER:

PERSON CALLED:

Jeff Kirk, CRMT

OFFICE/ADDRESS:

Healthsouth Diagnostic
Center, Anchorage

PHONE NUMBER:

907-563-3493

CONVERSATION

SUBJECT -

Ownership chg. lic. amendment

SUMMARY -

I called Kirk re. 4/8/97 ownership chg. ltr.
He said Beth had written back requesting info.
+ they were working on a reply.

REFERRED TO:

☐ ADVISE ME ON ACTION
TAKEN

ACTION REQUESTED:

INITIALS:

DATE:

ACTION TAKEN:

INITIALS:

DATE:

HEALTHSOUTH[®]

HEALTHSOUTH DIAGNOSTIC CENTERS OF ANCHORAGE, LTD.
4003 LAKE OTIS PARKWAY SUITE 101
ANCHORAGE, ALASKA 99508-5211
(Formerly Anchorage Diagnostic Imaging Center, Inc.)



April 8, 1997

U. S. Nuclear Regulatory Commission
Region IV
Nuclear Material Safety Section
61' Ryan Plaza Drive, Suite 400
Arlington, Texas 76011-8064

RE: Radioactive Materials License #50-23214-01/Anchorage Diagnostic Imaging Center, Inc. NAME AND OWNERSHIP CHANGE.

To whom it may concern:

The purpose of this amendment is to change the facility name and ownership of the site listed on this Radioactive Materials License.

We request that the name for this license be changed to HEALTHSOUTH DIAGNOSTIC CENTERS OF ANCHORAGE, LTD. The new owner is Healthsouth Diagnostic Centers, 1 Healthsouth Parkway, Birmingham, AL 35243. The current location of use, 4003 Lake Otis Parkway, Suite 101, Anchorage, AK, remains the same.

In addition, please remove Ronald G. Shriver, M.D. as an authorized user on the license.

All other items concerning this byproduct materials license remains unchanged at this time. Please contact Tom Scott, CNMT, or Jeff Kirk, BSRT, CNMT at (907)563-3493 if additional information is required. I thank you in advance for your prompt attention regarding this matter.

Respectfully,

Kay Ladyman
Administrator

kl

Enclosure: Anchorage Diagnostic Imaging Center Check #4174 in the amount of \$440.00

572487