



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 500  
ARLINGTON, TEXAS 76011-8064

JUL - 1 1997

EA 97-300

C. Randy Hutchinson, Vice President  
Operations  
Arkansas Nuclear One  
Entergy Operations, Inc.  
1448 S.R. 333  
Russellville, Arkansas 72801-0967

SUBJECT: NRC INSPECTION REPORT 50-313/97-03; 50-368/97-03 AND NOTICE OF VIOLATION

Dear Mr. Hutchinson:

An NRC inspection was conducted April 27 through June 7, 1997, at your Arkansas Nuclear One, Units 1 and 2, reactor facility. The enclosed report presents the scope and results of that inspection.

During the 6-week period covered by this inspection, your conduct of activities at the ANO facility was generally characterized by safety-conscious operations, sound engineering and maintenance practices, and appropriate radiological controls. Two violations of NRC requirements were identified. The first violation resulted from a failure to unisolate an emergency feedwater pump suction pressure transmitter. Although this violation satisfied the criteria to be noncited pursuant to Section VII.B.1 of the NRC's Enforcement Policy, it is being cited to emphasize the importance of using effective administrative controls to ensure the proper alignment of risk significant safety systems. The NRC has concluded that information regarding the reason for the violation and the corrective actions taken and planned to correct the violation and prevent recurrence is already adequately addressed on the docket in Licensee Event Report 50-368/97-002-00 dated March 6, 1997. Therefore, you are not required to respond to this letter unless the description herein does not accurately reflect your corrective actions or your position. In that case, or if you choose to provide additional information, you should follow the instructions specified in the enclosed Notice.

The second violation resulted from the placement of a Unit 2 fuel assembly in a location in the spent fuel pool which was prohibited by Technical Specifications. As a result of calculation errors and the failure to perform a required independent verification of the calculations prior to fuel movement, a total of 14 fuel assemblies would have been placed in locations prohibited by Technical Specifications had the error not been identified. Although subsequent analysis demonstrated that fuel in the spent fuel pool would have remained subcritical, procedures to ensure that fuel placed in the spent fuel pool remains in a subcritical configuration were not properly utilized by reactor engineers.

9707080350 970701  
PDR ADOCK 0500C313  
Q PDR




These violations are cited in the enclosed Notice of Violation (Notice) and the circumstances surrounding the violations are described in detail in the enclosed report. Please note that you are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. The NRC will use your response, in part, to determine whether further enforcement action is necessary to ensure compliance with regulatory requirements.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure(s), and your response will be placed in the NRC Public Document Room (PDR). To the extent possible, your response should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



Thomas P. Gwynn, Director  
Division of Reactor Projects

Docket Nos.: 50-313  
50-368  
License Nos.: DPR-51  
NPF-6

Enclosures:

1. Notice of Violation
2. NRC Inspection Report  
50-313/97-03; 50-368/97-03

cc w/enclosures:

Executive Vice President  
& Chief Operating Officer  
Entergy Operations, Inc.  
P.O. Box 31995  
Jackson, Mississippi 39286-1995

Vice President  
Operations Support  
Entergy Operations, Inc.  
P.O. Box 31995  
Jackson, Mississippi 39286

Manager, Washington Nuclear Operations  
ABB Combustion Engineering Nuclear  
Power  
12300 Twinbrook Parkway, Suite 330  
Rockville, Maryland 20852

County Judge of Pope County  
Pope County Courthouse  
Russellville, Arkansas 72801

Winston & Strawn  
1400 L Street, N.W.  
Washington, D.C. 20005-3502

David D. Snellings, Jr., Director  
Division of Radiation Control and  
Emergency Management  
Arkansas Department of Health  
4815 West Markham Street, Mail Slot 30  
Little Rock, Arkansas 72205-3867

Manager  
Rockville Nuclear Licensing  
Framatome Technologies  
1700 Rockville Pike, Suite 525  
Rockville, Maryland 20852

JUL - 1 1997

E-Mail report to T. Boyce (THB)  
 E-Mail report to NRR Event Tracking System (IPAS)  
 E-Mail report to Document Control Desk (DOCDESK)  
 E-Mail report to Richard Correia (RPC)  
 E-Mail report to Frank Talbot (FXT)

bcc to DCD (IE01)

bcc distrib. by RIV:

Regional Administrator

Resident Inspector

DRP Director

MIS System

Branch Chief (DRP/C)

RIV File

Project Engineer (DRP/C)

DRS-PSB

Branch Chief (DRP/TSS)

G. F. Sanborn, EO

W. L. Brown, RC

J. Lieberman, OE, MS: 7-H5

OE:EA File, MS: 7-H5

DOCUMENT NAME: R:\\_ANO\ANO703RP.KMK

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:SRI		C:DRP/C		D:DRP				
KMKennedy	<i>AK</i>	EECollins	<i>AK</i>	TPGwynn	<i>AK</i>			
6/20/97	<i>for</i>	6/20/97	<i>for</i>	6/20/97	<i>for</i>			

OFFICIAL RECORD COPY

JUL - 1 1997

E-Mail report to T. Boyce (THB)  
 E-Mail report to NRR Event Tracking System (IPAS)  
 E-Mail report to Document Control Desk (DOCDESK)  
 E-Mail report to Richard Correia (RPC)  
 E-Mail report to Frank Talbot (FXT)

bcc to DCD (IE01)

bcc distrib. by RIV:

Regional Administrator

DRP Director

Branch Chief (DRP/C)

Project Engineer (DRP/C)

Branch Chief (DRP/TSS)

G. F. Sanborn, EO

W. L. Brown, RC

J. Lieberman, OE, MS: 7-H5

OE:EA File, MS: 7-H5

Resident Inspector

MIS System

RIV File

DRS-PSB

DOCUMENT NAME: R:\\_ANO\ANO703RP.KMK

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:SRI		C:DRP/C		D:DRP				
KMKennedy	<i>A</i>	EECollins	<i>A</i>	TPGwynn	<i>A</i>			
6/20/97	<i>for</i>	6/30/97	<i>for</i>	6/30/97	<i>for</i>			

OFFICIAL RECORD COPY