



Materials Inspection Record

1. Licensee Name: CAVA Associates, P.C.		2. Docket Number(s): 030-35016		3. License Number(s): 21-32177-01	
4. Report Number(s): 2022-001			5. Date(s) of Inspection: January 5, 2022		
6. Inspector(s): D. A. Piskura		7. Program Code(s): 02201		8. Priority: 5	9. Inspection Guidance Used: 87130
10. Licensee Contact Name(s): Joseph Mueller, RSO		11. Licensee E-mail Address: jmueller@cava.cc		12. Licensee Telephone Number(s): 248-365-6896	
13. Inspection Type: <input checked="" type="checkbox"/> Routine <input type="checkbox"/> Announced <input type="checkbox"/> Non-Routine <input checked="" type="checkbox"/> Unannounced		14. Locations Inspected: <input checked="" type="checkbox"/> Main Office <input checked="" type="checkbox"/> Field Office <input type="checkbox"/> Temporary Job Site <input type="checkbox"/> Remote		15. Next Inspection Date (MM/DD/YYYY): 01/05/2027 <input checked="" type="checkbox"/> Normal <input type="checkbox"/> Extended <input type="checkbox"/> Reduced <input type="checkbox"/> No change	

16. Scope and Observations:

This multi-specialty doctor's owned out-patient cardiac clinic is authorized to use materials permitted by Section 35.200. The licensee operated three locations of use. The clinics located in Bloomfield Hills and Clarkston were open Monday-Friday. The licensee's newest clinic in Commerce Township opened in November 2021 and conducted patient studies on Mondays, Wednesdays, and Thursdays. Each clinic site was staffed with a full-time technologist. This inspection included a review of the licensee's clinics located in Bloomfield Hills and Commerce Township, Michigan. Collectively, the licensee administered approximately 200-250 diagnostic studies per month. The licensee received unit doses from a local radiopharmacy. The licensee retained the services of a consulting physicist who audited the radiation safety program of each clinic location on a quarterly basis; the recent audits performed during the fourth quarter of 2021 identified no findings or violations.

During this inspection, the inspector interviewed licensee personnel; observed three patient exercise stress test procedures; observed package receipts and surveys; performed independent, confirmatory surveys; and reviewed select records. The inspector reviewed a selected sample of patient scripts, and records of package receipt surveys and wipe tests, dose calibrator QA/QC, quarterly audit reports by the consultant, training, leak tests, waste disposal, and personnel dosimetry.

No violations of NRC requirements were identified during this inspection.

MX
1-13-2022