

From: [Brost, Wendy](#)
To: [Habib, Donald](#)
Cc: [Galvin, Dennis](#)
Subject: [External_Sender] STP ISFSI - request for public call
Date: Thursday, February 24, 2022 5:01:27 PM

Donald –

STP is requesting a call to discuss a planned emergent relief/exemption request related to a non-compliance with ASME code testing requirements for repaired welds. I spoke with our dry cask team, and they could be ready for a call as early as 3/7/22.

The vendor cannot find documentation to prove that 100% of the weld was inspected as required – 98% of the inspection was completed. Approximately 1” of the weld was not inspected as required. The vendor is aware of where this 1” section is, and noted that it is not the area where the defect was found that required repair. This affects 4 of the casks as STP, one of which has already been loaded with fuel.

Currently, we are on a loading campaign movement hold. Our conclusion was that we couldn’t lower the affected loaded MPC into its overpack with this question of code non-compliance open, so it is currently located in the hi-track transfer cask, contributing to higher dose in the area.

- Wendy Brost
Supervisor, STPNOC Licensing