

James S. Baumstark
Vice President
Nuclear Engineering

Consolidated Edison Company of New York, Inc.
Indian Point 2 Station
Broadway & Bleakley Avenue
Buchanan, New York 10511

Internet: baumstarkj@coned.com
Telephone: (914) 734-5354
Cellular: (914) 391-9005
Pager: (917) 457-9698
Fax: (914) 734-5718

December 21, 1999

Re: Indian Point Unit No. 2
Docket No. 50-247

Document Control Desk
US Nuclear Regulatory Commission
Mail Station P1-137
Washington, DC 20555

Subject: 10 CFR §50.59(b) Report for Indian Point Unit No. 2

Pursuant to 10 CFR §50.59(b)(2), enclosed please find a report of the changes, tests and experiments conducted at Indian Point Unit No. 2 during the period June 22, 1997 to June 21, 1999. The changes set forth in the report represent the changes made to the facility as defined in the Indian Point Unit No. 2 Final Safety Analysis Report pursuant to 10 CFR §50.59(b)(1).

Should you or your staff have any questions regarding this matter please contact Mr. John McCann, Manager, Nuclear Safety and Licensing.

Very Truly Yours,



IE47

PDL ADDON 0500 0247

cc: Mr. Hubert J. Miller
Regional Administrator-Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Jefferey F. Harold, Project Manager
Project Directorate I-1
Division of Reactor Projects I/II
US Nuclear Regulatory Commission
Mail Stop 14B-2
Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511