



A Subsidiary of RGS Energy Group, Inc.

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001 • 716 546-2700

www.rge.com

ROBERT C. MECREDY
Vice President
Nuclear Operations

August 17, 2000

U.S. Nuclear Regulatory Commission
Document Control Desk
Attn: Guy S. Vissing
Project Directorate I
Washington, D.C. 20555

Subject: LER 2000-S01, Safeguards Event
R.E. Ginna Nuclear Power Plant
Docket No. 50-244

Dear Mr. Vissing:

The attached Licensee Event Report LER 2000-S01 is submitted in accordance with 10 CFR 73.71 and Section I(d) of Appendix G, Reportable Safeguards Events.

Very truly yours,



Robert C. Mecredy

xc: Mr. Guy S. Vissing (Mail Stop 8C2)
Project Directorate I
Division of Licensing Project Management
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

U.S. NRC Ginna Senior Resident Inspector

IE74

1000171

LICENSEE EVENT REPORT (LER)

(See reverse for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request: 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Forward comments regarding burden estimate to the Records Management Branch (T-6 F33), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, and to the Paperwork Reduction Project (3150-0104), Office of Management and Budget, Washington, DC 20503. If an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

FACILITY NAME (1)

R. E. Ginna Nuclear Power Plant

DOCKET NUMBER (2)

05000244

PAGE (3)

1 OF 3

TITLE (4)

Safeguards Event

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
07	18	2000	2000	S01	00	08	17	2000	FACILITY NAME	DOCKET NUMBER
										05000
										05000
OPERATING MODE (9)		1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)							
			20.2201(b)			20.2203(a)(2)(v)			50.73(a)(2)(i)	
			20.2203(a)(1)			20.2203(a)(3)(i)			50.73(a)(2)(ii)	
			20.2203(a)(2)(i)			20.2203(a)(3)(ii)			50.73(a)(2)(iii)	
			20.2203(a)(2)(ii)			20.2203(a)(4)			50.73(a)(2)(iv)	
			20.2203(a)(2)(iii)			50.36(c)(1)			50.73(a)(2)(v)	
			20.2203(a)(2)(iv)			50.36(c)(2)			50.73(a)(2)(vii)	
POWER LEVEL (10)		100	OTHER							
			Specify in Abstract below or in NRC Form 366A							

LICENSEE CONTACT FOR THIS LER (12)

NAME

Ronald C. Teed - Manager, Nuclear Security

TELEPHONE NUMBER (Include Area Code)

(716) 771-3232

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

SUPPLEMENTAL REPORT EXPECTED (14)

YES
(If yes, complete EXPECTED SUBMISSION DATE).

X NO

EXPECTED
SUBMISSION
DATE (15)

MONTH

DAY

YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On July 18, 2000, at approximately 1845 EDST, a security event was identified and determined to be reportable to the Nuclear Regulatory Commission in accordance with 10CFR73.71, Appendix G, Section I(d). It was determined there was an attempted introduction of contraband into the Ginna Station Protected Area. The contraband was discovered during a routine entry search of a vehicle. The vehicle and driver were denied access to the Protected Area.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
R. E. Ginna Nuclear Power Plant	05000244	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 3
		2000	- S01 -	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

I. Pre-Event Plant Conditions

The plant was in Mode 1, at approximately 100% steady state reactor power.

II. Description of Event

On July 18, 2000, a routine vehicle search was conducted for a tractor-trailer operated by an out-of-state transporter who was delivering equipment to the plant. The delivery was expected and authorized. During this search, an unauthorized weapon (.357 caliber handgun) was discovered. Upon discovery of the weapon in the cab of the tractor-trailer, the searching security officer immediately notified the Security Shift Supervisor and Secondary Alarm Station Operator controlling the Protected Area vehicle access gates. The search was stopped and both vehicle and driver were denied access to the Protected Area. Security and plant management were notified, including the Operations Shift Supervisor and the Vice President/Plant Manager. The driver was interviewed by the Manager, Nuclear Security and the Nuclear Security Operations Coordinator.

During the interview it was determined that there did not appear to be any evidence of malicious intent to use the weapon. However, there was evidence, based on written and verbal responses of the driver during the interview, that the driver was aware of the weapon in the vehicle and did not intend to declare it. The driver could give no clear reason for not declaring the weapon and his explanations included non-credible and conflicting statements.

The Wayne County Sheriff's Department was notified and a deputy responded to the scene. The deputy interviewed the driver, secured the weapon, and discussed the circumstances with his supervisor and the District Attorney. The District Attorney was unable to develop a basis for filing any charges, therefore no charges were filed. The driver was given a stern warning and his weapon was returned to him after he left Rochester Gas & Electric Corporation property.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2) NUMBER (2)	LER NUMBER (6)			PAGE (3)
R. E. Ginna Nuclear Power Plant	05000244	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 3
		2000	- S01	- 00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

III. Event Summary

All procedures were properly implemented during this event. It was deemed there was no apparent threat against the facility. The delivered equipment was unloaded in the parking lot outside of the Protected Area and the driver and vehicle departed. The event was determined reportable under 10 CFR 73.71, Section I(d) of Appendix G, Reportable Safeguards Events, and NRC Regulatory Guide 5.62.

IV. Corrective Action

Corrective action was accomplished by denying access to the Protected Area and investigations into the incident by security management and local law enforcement personnel.