

December 6, 2000

Mr. Peter S. Hastings  
Duke Cogema Stone & Webster  
P.O. Box 31847  
Charlotte, NC 28231-1847

SUBJECT: RESIDENT INSPECTOR OFFICE SPACE REQUIREMENTS

Dear Mr. Hastings:

In your letter of August 28, 2000, you provided a proposed conceptual arrangement for Nuclear Regulatory Commission inspector offices in the Mixed Oxide Fuel Fabrication Facility Administrative Building. You asked us to review the proposed arrangement and provide our concurrence.

NRC considers the amount of space adequate, but requires a modified arrangement. Since the resident inspectors will have a secretary/receptionist, the main entrance to the NRC residents' office area needs to be at the secretary's desk. The NRC residents' offices should be on one side of the secretarial area with the conference room on the other side of the secretarial area. This would provide needed privacy for the residents and visiting inspectors. The modified layout may require adjustment of room sizes.

If you have any further questions, please contact me at (301) 415-6522.

Sincerely,

/RA/

Andrew Persinko, Project Manager  
Enrichment Section  
Special Projects Branch  
Division of Fuel Cycle Safety  
and Safeguards, NMSS

Docket: 70-3098

cc: Mr. James Johnson, DOE  
Mr. Henry Potter, SC Dept of Health &  
Environmental Control  
Mr. John T. Conway, Chairman, DNFSB

Mr. Peter S. Hastings  
Duke Cogema Stone & Webster  
P.O. Box 31847  
Charlotte, NC 28231-1847

SUBJECT: RESIDENT INSPECTOR OFFICE SPACE REQUIREMENTS

Dear Mr. Hastings:

In your letter of August 28, 2000, you provided a proposed conceptual arrangement for Nuclear Regulatory Commission inspector offices in the Mixed Oxide Fuel Fabrication Facility Administrative Building. You asked us to review the proposed arrangement and provide our concurrence.

NRC considers the amount of space adequate, but requires a modified arrangement. Since the resident inspectors will have a secretary/receptionist, the main entrance to the NRC residents' office area needs to be at the secretary's desk. The NRC residents' offices should be on one side of the secretarial area with the conference room on the other side of the secretarial area. This would provide needed privacy for the residents and visiting inspectors. The modified layout may require adjustment of room sizes.

If you have any further questions, please contact me at (301) 415-6522.

Sincerely,

/RA/

Andrew Persinko, Project Manager  
Enrichment Section  
Special Projects Branch  
Division of Fuel Cycle Safety  
and Safeguards, NMSS

Docket: 70-3098

cc: Mr. James Johnson, DOE  
Mr. Henry Potter, SC Dept of Health &  
Environmental Control  
Mr. John T. Conway, Chairman, DNFSB

DISTRIBUTION:

Docket 70-3098      ADAMS      PUBLIC      SPB r/f      FCSS r/f  
ELeeds      EMcAlpine, RII      DAgres, RII

ADAMS Accession#: ML003774678

DOCUMENT NAME: G:\SPB\tcj\moxinspectspace.wpd      \*SEE PREVIOUS CONCURRENCE

| OFC  | SPB          |  | SPB       | E | SPB        |  | SPB       |  |
|------|--------------|--|-----------|---|------------|--|-----------|--|
| NAME | TJohnson:dr* |  | DHoadley* |   | APersinko* |  | MGalloway |  |
| DATE | 12/1/00      |  | 12/4/00   |   | 12/4/00    |  | 12/6/00   |  |

C-COVER

E-COVER & ENCLOSURE  
OFFICIAL RECORD COPY

N-NO COPY