

50-397

- ++ Procedure Control assures delivery is arranged/made to J. Ittner
- Level 1 File

A 045

- 3.42 Coordinate use of Energy Northwest radiological equipment and manpower resources, authorized by the EOF Manager, to provide assistance to the state in establishing relocation centers, food control zones, or other reentry and recovery activities.
- 3.43 Refer all calls from media to the JIC.
- 3.44 Upon shift change, turn over chronological logs and brief your relief on the current status of the emergency, radiological activities, and status of work being performed.
- 3.45 Upon shift change or termination of the emergency:
- Prepare an individual After Action Report. Refer to PPM 13.13.4
 - Collect individual After Action Reports prepared by staff personnel.
 - Deliver all After Action Reports and accompanying sheets to the EOF Manager.

4.0 ATTACHMENTS

- 4.1 Checklist for Radiological Emergency Manager Duties
- 4.2 Dose Projection Health Physicist Duties
- 4.3 Comparison of Field Data with Dose Projections
- 4.4 Health Physics Network (HPN) Communicator Duties
- 4.5 Health Physics Center (HPC) Staff
- 4.6 Health Physics Center Staff Radiological Sample Tracking Instructions
- 4.7 Typical Setup for HP Center Receiving Area
- 4.8 Radiological Emergency Manager Briefing Guidelines
- 4.9 Total Population Within the 10 Mile EPZ
- 4.10 EOF HVAC Automatic and Manual Operation
- 4.11 Dose Assessment Center Leadership Transfer Guide

PROCEDURE NUMBER	REVISION	PAGE
13.11.7	23	10 of 31