

SFP

2/4/00

CT:

→ Hubbard brought over revised pages.
He just missed one of our proposed changes.
Farout will now forward the package through
RES again for concurrence.

→ checking failure and
zirconium oxidation temperatures

565°C Very conservative (10 hours)

MECCOR	900°C
MAAP	930°C

F119