

601-1

5/15/00

L. Dickson:

A couple of hours at temperature

CS release, then Ru release

(then more plus X. NO<sub>2</sub> + )

There is 1000 sec delay between the CS release and the Ru release.

lost bundle  
• guillotine failure of pressure tube  
• rod bundle gets ejected  
(NO<sub>2</sub>)