



P.O. Box 1098 • Roseboro, N.C. 28382
(919) 525-4161

Pt 21. 84-328
Publicly Available
D208
N187

To Ray Smith

May 15, 1984

TO: Jerome Blake
Director Region II
Office of Inspection & Enforcement
US NRC
101 Marietta St. N. W. Suite 2900
Atlanta, GA 30303

SUBJECT: Non Conforming Material (10CFR21)

Dear Sir:

It has come to our attention that some material that was supplied by DuBose Steel could be a potential 10CFR21 reportable item. This material was originally purchased from Northwestern Steel & Wire Company.

The material involved was W6 x 20# beams heat numbers 80551 and 77052 and W6 x 25# beams heat number 89728. This material is reported as having twisted or skewed webs in heat numbers 77052 and 80551, the area is reported as 5.06% low on heat number 89728.

These potential problems were reported to DuBose Steel on 5-14-84 by Daniel International Corporation, P.O. Box 146, Strawn, KS 66839.


Northwestern Steel & Wire Company is aware of these problems and is studying the problem. A copy of this report will be forwarded to you as soon as it is received. Please contact me at DuBose Steel

JE19

if there are any questions.

Below is a list of nine DuBose Steel customers which have received material from these heat numbers. We will be contacting these customers by phone and letter.

DuBose Steel Incorporated,



James N. Dailey
Quality Assurance Manager

JND:bs

cc: Bechtel Power Corporation
Port Gibson, Mississippi

Corner & Lada Corporation
Cranston, RI

Daniel International
Fulton, MO

Duke Power Corporation
Charlotte, N. C.

Florida Power & Light
Florida City, Florida

Houston Lighting & Power
Bay City, Texas

Johnson Controls
Perry, Ohio

NPS Industries
Austin, Texas

Power Piping Company
Pittsburgh, PA

cc: Doug Apperson
William R. Bennett