



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**
WASHINGTON, D.C. 20555-0001

April 3, 2001

LICENSEE: Exelon Generating Company, LLC

FACILITY: Peach Bottom Atomic Power Station Units 2 and 3

SUBJECT: SUMMARY OF MEETING BETWEEN THE U.S. NUCLEAR REGULATORY COMMISSION (NRC) STAFF AND EXELON CORPORATION REPRESENTATIVES TO DISCUSS THE PEACH BOTTOM LICENSE RENEWAL APPLICATION

On March 29, 2001, the U.S. Nuclear Regulatory Commission (NRC) staff met with representatives from Exelon Corporation to discuss the status, the format and the content of the Peach Bottom License Renewal application. Exelon provided an overview of the application and discussed the NRC/Exelon communications process following the application submittal. A list of meeting attendees is provided in Enclosure 1. Exelon presentation materials are provided in Enclosure 2.

Exelon discussed the improvements made from the lessons learned from the review of the Hatch license renewal application and the staff's draft safety evaluation report. In addition, Exelon discussed the ongoing interaction between the industry and the NRC staff in their preparation of the application. Exelon stated that the Peach Bottom license renewal application is aligned with the Standard Review Plan (SRP) for the review of license renewal application but will not reference the Generic Aging Lessons Learned (GALL) report. The application includes discussion of existing, enhanced, and new aging management programs in Appendix B. The Table of Contents of the application is provided in Enclosure 3.

The Exelon presentation provided the staff with an understanding of the Peach Bottom license renewal application development process, which will be beneficial during the staff's review of the application materials. Exelon plans to submit the Peach Bottom license renewal application on July 2, 2001.

Raj K. Anand

Raj K. Anand, Project Manager
License Renewal and Standardization Branch
Division of Regulatory Improvement Programs
Office of Nuclear Reactor Regulation

Docket Nos. 50-277 and 50-278

Enclosure: As stated

cc w/encl: See next page

April 3, 2001

LICENSEE: Exelon Generating Company, LLC

FACILITY: Peach Bottom Atomic Power Station Units 2 and 3

SUBJECT: SUMMARY OF MEETING BETWEEN THE U.S. NUCLEAR REGULATORY COMMISSION (NRC) STAFF AND EXELON CORPORATION REPRESENTATIVES TO DISCUSS THE PEACH BOTTOM LICENSE RENEWAL APPLICATION

On March 29, 2001, the U.S. Nuclear Regulatory Commission (NRC) staff met with representatives from Exelon Corporation to discuss the status, the format and the content of the Peach Bottom License Renewal application. Exelon provided an overview of the application and discussed the NRC/Exelon communications process following the application submittal. A list of meeting attendees is provided in Enclosure 1. Exelon presentation materials are provided in Enclosure 2.

Exelon discussed the improvements made from the lessons learned from the review of the Hatch license renewal application and the staff's draft safety evaluation report. In addition, Exelon discussed the ongoing interaction between the industry and the NRC staff in their preparation of the application. Exelon stated that the Peach Bottom license renewal application is aligned with the Standard Review Plan (SRP) for the review of license renewal application but will not reference the Generic Aging Lessons Learned (GALL) report. The application includes discussion of existing, enhanced, and new aging management programs in Appendix B. The Table of Contents of the application is provided in Enclosure 3.

The Exelon presentation provided the staff with an understanding of the Peach Bottom license renewal application development process, which will be beneficial during the staff's review of the application materials. Exelon plans to submit the Peach Bottom license renewal application on July 2, 2001.

/RA/

Raj K. Anand, Project Manager
License Renewal and Standardization Branch
Division of Regulatory Improvement Programs
Office of Nuclear Reactor Regulation

Docket Nos. 50-277 and 50-278
Enclosure: As stated
cc w/encl: See next page

DISTRIBUTION: See next page

Document Name: G:\RLSB\ANAND\peach bottom sum.wpd

*See previous concurrence

OFFICE	LA	PM:RLSB	BC:RLSB
NAME	EGHylton	RKAnand <i>R. Anand</i> <i>4/3</i>	CIGrimes <i>CGI</i>
DATE	03/30/01	03/30/01	04/3/01

OFFICIAL RECORD COPY

LICENSEE: Exelon Generating Company, LLC

FACILITY: Peach Bottom Atomic Power Station Units 2 and 3

SUBJECT: SUMMARY OF MEETING BETWEEN THE U.S. NUCLEAR REGULATORY COMMISSION (NRC) STAFF AND EXELON CORPORATION REPRESENTATIVES TO DISCUSS THE PEACH BOTTOM LICENSE RENEWAL APPLICATION

On March 29, 2001, the U.S. Nuclear Regulatory Commission (NRC) staff met with representatives from Exelon Corporation to discuss the status, the format and the content of the Peach Bottom License Renewal application. Exelon provided an overview of the application and discussed the NRC/Exelon communications process following the application submittal. A list of meeting attendees is provided in Enclosure 1. Exelon presentation materials are provided in Enclosure 2.

Exelon discussed the improvements made from the lessons learned from the review of the Hatch license renewal application and the staff's draft safety evaluation report. In addition, Exelon discussed the use of the Generic Aging Lessons Learned (GALL) report and the ongoing interaction between the industry and the NRC staff in preparation of the application. Exelon stated that the Peach Bottom license renewal application is aligned with the Standard Review Plan (SRP) for the review of license renewal application. The application includes discussion of existing, enhanced, and new aging management programs in Appendix B. The Table of Contents of the application is provided in Enclosure 3.

The Exelon presentation provided the staff with an understanding of the Peach Bottom license renewal application development process, which will be beneficial during the staff's review of the application materials. Exelon plans to submit the Peach Bottom license renewal application on July 2, 2001.

Raj K. Anand, Project Manager
License Renewal and Standardization Branch
Division of Regulatory Improvement Programs
Office of Nuclear Reactor Regulation

Docket Nos. 50-277 and 50-278

Enclosure: As stated

cc w/encl: See next page

DISTRIBUTION: See next page

Document Name: G:\RLSB\ANAND\peach bottom sum.wpd

OFFICE	LA	PM:RLSB	BC:RLSB
NAME	EGHylton	RKAnand	CIGrimes
DATE	04/30/01	3/30/2001 04/ /01	04/ /01

OFFICIAL RECORD COPY

DISTRIBUTION:

HARD COPY

RLSB RF

E. Hylton

E-MAIL:

PUBLIC

J. Johnson

D. Matthews

C. Grimes

C. Carpenter

W. Beckner

B. Zalcman

J. Strosnider

R. Wessman

G. Bagchi

K. Manoly

W. Bateman

J. Calvo

C. Holden

P. Shemanski

J. Shea

G. Holahan

T. Collins

B. Thomas

B. Boger

J. Peralta

G. Galletti

J. Moore

M. Mayfield

S. Bahadur

A. Murphy

W. McDowell

S. Droggitis

RLSB Staff

S. Duraiswamy

J. Bosca

Peach Bottom Atomic Power Station, Units 2 and 3

cc:

Mr. Edward Cullen
Vice President & General Counsel
Exelon Generation Company, LLC
300 Exelon Way
Kennett Square, PA 19348

Mr. J. Doering
Site Vice President
Peach Bottom Atomic Power Station
1848 Lay Road
Delta, PA 17314

Mr. G. Johnston
Plant Manager
Peach Bottom Atomic Power Station
1848 Lay Road
Delta, PA 17314

Mr. A. Winter
Regulatory Assurance Manager
Peach Bottom Atomic Power Station
1848 Lay Road
Delta, PA 17314

Resident Inspector
U.S. Nuclear Regulatory Commission
Peach Bottom Atomic Power Station
P.O. Box 399
Delta, PA 17314

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Roland Fletcher
Department of Environment
Radiological Health Program
2400 Broening Highway
Baltimore, MD 21224

A. F. Kirby, III
External Operations - Nuclear
Delmarva Power & Light Company
P.O. Box 231
Wilmington, DE 19899

Chief-Division of Nuclear Safety
PA Dept. of Environmental Resources
P.O. Box 8469
Harrisburg, PA 17105-8469

Board of Supervisors
Peach Bottom Township
R. D. #1
Delta, PA 17314

Public Service Commission of Maryland
Engineering Division
Chief Engineer
6 St. Paul Center
Baltimore, MD 21202-6806

Mr. Richard McLean
Power Plant and Environmental
Review Division
Department of Natural Resources
B-3, Tawes State Office Building
Annapolis, MD 21401

Dr. Judith Johnsrud
National Energy Committee
Sierra Club
433 Orlando Avenue
State College, PA 16803

Manager-Financial Control & Co-Owner
Affairs
Public Service Electric and Gas Company
P.O. Box 236
Hancocks Bridge, NJ 08038-0236

Correspondence Control Desk
Exelon Generation Company, LLC
200 Exelon Way, KSA 1-N-1
Kennett Square, PA 19348

Mr. Jeffrey A. Benjamin
Vice President-Licensing
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, IL 60515

Mr. James A. Hutton
Director - Licensing
Mid-Atlantic Regional Operating Group
Exelon Generation Company, LLC
200 Exelon Way, KSA 3-E
Kennett Square, PA 19348

Mr. Joseph Hagan
Senior Vice President
Mid-Atlantic Regional Operating Group
Exelon Generation Company, LLC
200 Exelon Way, KSA 3-N
Kennett Square, PA 19348

Mr. John Skolds
Chief Operating Officer
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, IL 60515

Mr. William Bohlke
Senior Vice President, Nuclear Services
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, IL 60515

Mr. John Cotton
Senior Vice President, Operations Support
Exelon Generation Company, LLC
1400 Opus Place, Suite 900
Downers Grove, IL 60515

Mr. Douglas J. Walters
Nuclear Energy Institute
1776 I Street, N.W., Suite 400
Washington, DC 20006-3708

Mr. Fred Polaski
Exelon License Renewal Manager
200 Exelon Way
Kennett Square, PA 19348

ATTENDANCE LIST
March 29, 2001
NRC Meeting with Exelon Corporation
License Renewal for Peach Bottom, Units 2 & 3
(10 CFR Part 54 and 51)

<u>Name</u>	<u>Organization</u>
1. Raj Anand	NRC/NRR/DRIP/RLSB
2. John Boska	NRC/NRR/DLPM
3. Jerry Phillabaum	Exelon
4. John Hilbish	Parsons
5. Jim Hutton	Exelon
6. Erach Patel	Exelon
7. Fred Polaski	Exelon
8. Dave Honan	Exelon
9. Bill Moher	Exelon
10. Steve Hoffman	NRC/NRR/DRIP/RLSB
11. Paul Shemanski	NRC/NRR/DE/EEIB
12. Amar Pal	NRC/NRR/DE/EEIB
13. Saba Saba	NRC/NRR/DE/EEIB
14. Chris Grimes	NRC/NRR/DRIP/RLSB
15. Goutam Bagchi	NRC/NRR/DE
16. Brian Thomas	NRC/NRR/DSSA/SPLB
17. Dennis Dyckman	P. A. Dept. of Environment Protection
18. Paul Bessette	MLB

Enclosure 1

Peach Bottom Atomic Power Station License Renewal Application

Exelon Nuclear

March 29, 2001

Purpose

- Present status and format for Peach Bottom Atomic Power Station License Renewal Application (LRA) – Parts 54 and 51
- Discuss NRC/Exelon Communications Process Following Submittal

Status of Application

- LRA Aligned with Standard Review Plan
 - LRA Format Incorporated Lessons Learned
- Added Program Descriptions in Appendix B
- Prepared Severe Accident Mitigation Alternatives Evaluation
- Coordinating LRA with Industry Peers

Status of LRA

- Prepared and Reviewed Interim Draft LRA (complete)
- Prepared Final Draft LRA (complete)
 - Table of Contents for each Section

Reviews of Final Draft LRA

- Peach Bottom Station Personnel (By 3/30)
- Exelon Nuclear Corporate (By 3/30)
- Industry Peers (By 4/26)
- Plant Operations Review Committee (5/15)
- Nuclear Safety Review Board (6/8)
- Exelon Nuclear Management (By 6/19)

Proposed Exelon/NRC Interfaces Following Submittal

- Teleconferences
 - Identify areas requiring clarification and set follow-up teleconference/meeting
 - Conduct resolution teleconference
- Meetings
 - Overview of LRA (Week of July 23)
 - Clarify information to resolve potential RAIs
 - Clarify RAI responses

Issues Requiring Further Discussion

- Pre-Planning for Part 54 and Part 51 Reviews
 - Establish Communication Protocol
 - Schedule Resources
- Coordination of LRA Review with Fall 2001 Plant Outage Schedules
- Coordination and Timing of RAI

SECTION 1.0 ADMINISTRATIVE INFORMATION

<u>1.1</u>	GENERAL INFORMATION - 10 CFR 54.19	1-1
<u>1.1.1</u>	Names of Applicant and Co-Owners.....	1-1
<u>1.1.2</u>	Addresses of Applicant and Co-Owners	1-1
<u>1.1.3</u>	Description of Business or Occupation of Applicant and Co-Owners.....	1-1
<u>1.1.4</u>	Description of Organization and Management of Applicant and Co-Owners	1-2
<u>1.1.5</u>	Class of License, Use of the Facility and Period of Time for Which the License is Sought.....	1-10
<u>1.1.6</u>	Earliest and Latest Dates for Alterations, if Proposed.....	1-10
<u>1.1.7</u>	Restricted Data	1-10
<u>1.1.8</u>	Regulatory Agencies	1-10
<u>1.1.9</u>	Local News Publications	1-11
<u>1.1.10</u>	Conforming Changes to Standard Indemnity Agreement	1-12
<u>1.2</u>	GENERAL LICENSE INFORMATION	1-13
<u>1.2.1</u>	Application Updates, Renewed Licenses, and Renewal Term Operation	1-13
<u>1.2.2</u>	Incorporation by Reference.....	1-13
<u>1.2.3</u>	Contact Information.....	1-13
<u>1.3</u>	PURPOSE	1-14
<u>1.4</u>	DESCRIPTION OF THE PLANT.....	1-15
<u>1.5</u>	APPLICATION STRUCTURE	1-16
<u>1.6</u>	ACRONYMS	1-19
<u>1.7</u>	GENERAL REFERENCES	1-22

SECTION 2.0 STRUCTURES AND COMPONENTS SUBJECT TO AGING MANAGEMENT REVIEW

<u>2.1</u>	SCOPING AND SCREENING METHODOLOGY	2-1
<u>2.1.1</u>	Introduction	2-1
<u>2.1.2</u>	Scoping Methodology.....	2-2
<u>2.1.2.1</u>	Systems, Structures, and Components within the Scope of License Renewal	2-2
<u>2.1.2.2</u>	Intended Functions of SSCs within the Scope of License Renewal.....	2-10
<u>2.1.3</u>	Screening Methodology	2-12
<u>2.2</u>	PLANT LEVEL SCOPING RESULTS	2-15
<u>2.3</u>	SCOPING AND SCREENING RESULTS: MECHANICAL.....	2-25
<u>2.3.1</u>	Reactor Coolant System	2-26
<u>2.3.1.1</u>	Reactor Pressure Vessel and Internals	2-26
<u>2.3.1.2</u>	Fuel Assemblies.....	2-29
<u>2.3.1.3</u>	Reactor Pressure Vessel Instrumentation System.....	2-30
<u>2.3.1.4</u>	Reactor Recirculation System.....	2-32
<u>2.3.2</u>	Engineered Safety Features Systems.....	2-34
<u>2.3.2.1</u>	High Pressure Coolant Injection System	2-34
<u>2.3.2.2</u>	Core Spray System.....	2-38
<u>2.3.2.3</u>	Primary Containment Isolation System	2-41
<u>2.3.2.4</u>	Reactor Core Isolation Cooling System	2-43
<u>2.3.2.5</u>	Residual Heat Removal System	2-46
<u>2.3.2.6</u>	Containment Atmosphere Control and Dilution System.....	2-50
<u>2.3.2.7</u>	Standby Gas Treatment System	2-52
<u>2.3.2.8</u>	Secondary Containment	2-54
<u>2.3.3</u>	Auxiliary Systems.....	2-55
<u>2.3.3.1</u>	Fuel Handling Systems	2-55
<u>2.3.3.2</u>	Fuel Pool Cooling and Cleanup System	2-56
<u>2.3.3.3</u>	Control Rod Drive System.....	2-58
<u>2.3.3.4</u>	Standby Liquid Control System.....	2-60
<u>2.3.3.5</u>	High Pressure Service Water System.....	2-62
<u>2.3.3.6</u>	Emergency Service Water System	2-64
<u>2.3.3.7</u>	Fire Protection System	2-66
<u>2.3.3.8</u>	Control Room Ventilation System	2-70

<u>2.3.3.9</u>	Battery and Emergency Switchgear Ventilation System.....	2-72
<u>2.3.3.10</u>	Diesel Generator Building Ventilation System	2-74
<u>2.3.3.11</u>	Pump Structure Ventilation System	2-76
<u>2.3.3.12</u>	Safety Grade Instrument Gas System	2-78
<u>2.3.3.13</u>	Backup Instrument Nitrogen to ADS System.....	2-81
<u>2.3.3.14</u>	Emergency Cooling Water System	2-81
<u>2.3.3.15</u>	Condensate Storage System	2-83
<u>2.3.3.16</u>	Emergency Diesel Generator	2-85
<u>2.3.3.17</u>	Suppression Pool Temperature Monitoring System.....	2-98
<u>2.3.3.18</u>	Cranes and Hoists	2-90
 <u>2.3.4</u>	 Steam and Power Conversion Systems.....	 2-92
<u>2.3.4.1</u>	Main Steam System	2-92
<u>2.3.4.2</u>	Main Condenser.....	2-96
<u>2.3.4.3</u>	Feedwater System	2-98
 <u>2.4</u>	 SCOPING AND SCREENING RESULTS: STRUCTURES AND COMPONENT SUPPORTS	 2-100
 <u>2.4.1</u>	 Containment Structure	 2-101
<u>2.4.2</u>	Reactor Building Structure	2-104
<u>2.4.3</u>	Radwaste Building and Reactor Auxiliary Bay	2-107
<u>2.4.4</u>	Turbine Building and Main Control Room Complex	2-109
<u>2.4.5</u>	Emergency Cooling Tower and Reservoir.....	2-111
<u>2.4.6</u>	Station Blackout Structure and Foundation.....	2-113
<u>2.4.7</u>	Yard Structures	2-114
<u>2.4.8</u>	Stack	2-116
<u>2.4.9</u>	Nitrogen Storage Building	2-117
<u>2.4.10</u>	Diesel Generator Building	2-118
<u>2.4.11</u>	Circulating Water Pump Structure	2-120
<u>2.4.12</u>	Recombiner Building	2-122
<u>2.4.13</u>	Component Supports	2-123
<u>2.4.14</u>	Hazard Barriers	2-125
<u>2.4.15</u>	Miscellaneous Steel	2-127
<u>2.4.16</u>	Electrical and Instrumentation Enclosures and Raceways.....	2-128
<u>2.4.17</u>	Insulation.....	2-129
 <u>2.5</u>	 SCOPING AND SCREENING RESULTS: ELECTRICAL AND INSTRUMENTATION AND CONTROLS	 2-130
 <u>2.5.1</u>	 Cables	 2-132
<u>2.5.2</u>	Connectors, Splices, and Terminal Blocks	2-137
<u>2.5.3</u>	Station Blackout System	2-139

List of Tables

<u>2.1-1</u>	Component Intended Functions.....	2-14
<u>2.2-1</u>	Mechanical System Scoping Results.....	2-16
<u>2.2-2</u>	Structure Scoping Results	2-23
<u>2.2-3</u>	Electrical System Scoping Results	2-24
<u>2.3.1-1</u>	Component Groups Requiring Aging Management Review - Reactor Pressure Vessel and Internals	2-27
<u>2.3.1-2</u>	Component Groups Requiring Aging Management Review - Fuel Assemblies	2-29
<u>2.3.1-3</u>	Component Groups Requiring Aging Management Review - Reactor Pressure Vessel Instrumentation	2-31
<u>2.3.1-4</u>	Component Groups Requiring Aging Management Review - Reactor Recirculation System	2-33
<u>2.3.2-1</u>	Component Groups Requiring Aging Management Review - High Pressure Coolant Injection System	2-35
<u>2.3.2-2</u>	Component Groups Requiring Aging Management Review - Core Spray System.....	2-39
<u>2.3.2-3</u>	Component Groups Requiring Aging Management Review - Primary Containment Isolation System.....	2-42
<u>2.3.2-4</u>	Component Groups Requiring Aging Management Review - Reactor Core Isolation Cooling System	2-44
<u>2.3.2-5</u>	Component Groups Requiring Aging Management Review - Residual Heat Removal System	2-48
<u>2.3.2-6</u>	Component Groups Requiring Aging Management Review - Containment Atmosphere Control and Dilution System.....	2-51
<u>2.3.2-7</u>	Component Groups Requiring Aging Management Review - Standby Gas Treatment System	2-53
<u>2.3.2-8</u>	Component Groups Requiring Aging Management Review - Secondary Containment System	2-54
<u>2.3.3-1</u>	Component Groups Requiring Aging Management Review - Fuel Handling System	2-55
<u>2.3.3-2</u>	Component Groups Requiring Aging Management Review - Fuel Pool Cooling and Cleanup System	2-57
<u>2.3.3-3</u>	Component Groups Requiring Aging Management Review - Control Rod Drive System	2-59
<u>2.3.3-4</u>	Component Groups Requiring Aging Management Review - Standby Liquid Control System	2-61
<u>2.3.3-5</u>	Component Groups Requiring Aging Management Review - High Pressure Service Water System	2-63
<u>2.3.3-6</u>	Component Groups Requiring Aging Management Review - Emergency Service Water System	2-65

<u>2.3.2-7</u>	Component Groups Requiring Aging Management Review - Fire Protection System	2-67
<u>2.3.3-8</u>	Component Groups Requiring Aging Management Review - Control Room Ventilation System	2-71
<u>2.3.3-9</u>	Component Groups Requiring Aging Management Review - Battery and Emergency Switchgear Ventilation System	2-73
<u>2.3.3-10</u>	Component Groups Requiring Aging Management Review - Diesel Generator Building Ventilation System	2-75
<u>2.3.3-11</u>	Component Groups Requiring Aging Management Review - Pump Structure Ventilation System	2-77
<u>2.3.3-12</u>	Component Groups Requiring Aging Management Review - Safety Grade Instrument Gas	2-78
<u>2.3.3-13</u>	Component Groups Requiring Aging Management Review - Backup Nitrogen to ADS System	2-80
<u>2.3.3-14</u>	Component Groups Requiring Aging Management Review - Emergency Cooling Water System	2-82
<u>2.3.3-15</u>	Component Groups Requiring Aging Management Review - Condensate Storage System	2-84
<u>2.3.3-16</u>	Component Groups Requiring Aging Management Review - Emergency Diesel Generator System	2-85
<u>2.3.3-17</u>	Component Groups Requiring Aging Management Review - Suppression Pool Temperature Monitoring System	2-89
<u>2.3.3-18</u>	Component Groups Requiring Aging Management Review - Cranes and Hoists	2-91
<u>2.3.4-1</u>	Component Groups Requiring Aging Management Review - Main Steam System	2-94
<u>2.3.4-2</u>	Component Groups Requiring Aging Management Review - Main Condenser System	2-97
<u>2.3.4-3</u>	Component Groups Requiring Aging Management Review - Feedwater System	2-99
<u>2.4-1</u>	Component Groups Requiring Aging Management Review - Containment Structure	2-102
<u>2.4-2</u>	Component Groups Requiring Aging Management Review - Reactor Building Structure	2-105
<u>2.4-3</u>	Component Groups Requiring Aging Management Review - Radwaste Building and Reactor Auxiliary Bay	2-108
<u>2.4-4</u>	Component Groups Requiring Aging Management Review - Turbine Building and Main Control Room Complex	2-110
<u>2.4-5</u>	Component Groups Requiring Aging Management Review - Emergency Cooling Tower and Reservoir	2-112
<u>2.4-6</u>	Component Groups Requiring Aging Management Review - Station Blackout Structure and Foundation	2-113
<u>2.4-7</u>	Component Groups Requiring Aging Management Review - Yard Structures	2-115

Table of Contents

<u>2.4-8</u>	Component Groups Requiring Aging Management Review - Stack	2-116
<u>2.4-9</u>	Component Groups Requiring Aging Management Review - Nitrogen Storage Building	2-117
<u>2.4-10</u>	Component Groups Requiring Aging Management Review - Diesel Generator Building	2-119
<u>2.4-11</u>	Component Groups Requiring Aging Management Review - Circulating Water Pump Structure	2-121
<u>2.4-12</u>	Component Groups Requiring Aging Management Review - Recombiner Building.....	2-122
<u>2.4-13</u>	Component Groups Requiring Aging Management Review - Component Supports	2-124
<u>2.4-14</u>	Component Groups Requiring Aging Management Review - Hazard Barriers.....	2-125
<u>2.4-15</u>	Component Groups Requiring Aging Management Review - Miscellaneous Steel.....	2-127
<u>2.4-16</u>	Component Groups Requiring Aging Management Review - Electrical and Instrumentation Enclosures and Raceways	2-128
<u>2.4-17</u>	Component Groups Requiring Aging Management Review - Insulation	2-129
<u>2.5.1</u>	Component Groups Requiring Aging Management Review - Cables	2-134
<u>2.5-2</u>	Component Groups Requiring Aging Management Review - Connectors, Splices and Terminal Blocks	2-138
<u>2.5.3</u>	Component Groups Requiring Aging Management Review - Station Blackout System.....	2-141

List of Figures

<u>2.1-1</u>	Scoping and Screening Process Overview	2-3
<u>2.5-1</u>	Cable Group Temperature Review Process Overview.....	2-135

SECTION 3.0 AGING MANAGEMENT REVIEW RESULTS

<u>3.0</u>	INTRODUCTION.....	3-1
<u>3.1</u>	AGING MANAGEMENT OF REACTOR COOLANT SYSTEM	3-9
<u>3.1.1</u>	Reactor Pressure Vessel and Internals	3-10
<u>3.1.2</u>	Fuel Assemblies.....	3-14
<u>3.1.3</u>	Reactor Pressure Vessel Instrumentation System.....	3-15
<u>3.1.4</u>	Reactor Recirculation System.....	3-17
<u>3.2</u>	AGING MANAGEMENT OF ENGINEERED SAFETY FEATURES SYSTEMS.....	3-19
<u>3.2.1</u>	High Pressure Coolant Injection System	3-20
<u>3.2.2</u>	Core Spray System	3-33
<u>3.2.3</u>	Primary Containment Isolation System	3-41
<u>3.2.4</u>	Reactor Core Isolation Cooling System	3-44
<u>3.2.5</u>	Residual Heat Removal System	3-54
<u>3.2.6</u>	Containment Atmosphere Control and Dilution System	3-62
<u>3.2.7</u>	Standby Gas Treatment System	3-64
<u>3.2.8</u>	Secondary Containment System	3-66
<u>3.3</u>	AGING MANAGEMENT OF AUXILIARY SYSTEMS	3-67
<u>3.3.1</u>	Fuel Handling System	3-68
<u>3.3.2</u>	Fuel Pool Cooling and Cleanup System	3-69
<u>3.3.3</u>	Control Rod Drive System.....	3-70
<u>3.3.4</u>	Standby Liquid Control System.....	3-72
<u>3.3.5</u>	High Pressure Service Water System.....	3-74
<u>3.3.6</u>	Emergency Service Water System	3-79
<u>3.3.7</u>	Fire Protection System	3-82
<u>3.3.8</u>	Control Room Ventilation System	3-90
<u>3.3.9</u>	Battery and Emergency Switchgear Ventilation System	3-92
<u>3.3.10</u>	Diesel Generator Building Ventilation System	3-94
<u>3.3.11</u>	Pump Structure Ventilation System	3-95
<u>3.3.12</u>	Safety Grade Instrument Gas System	3-96
<u>3.3.13</u>	Backup Instrument Nitrogen to ADS System	3-97
<u>3.3.14</u>	Emergency Cooling Water System	3-98
<u>3.3.15</u>	Condensate Storage System	3-101
<u>3.3.16</u>	Emergency Diesel Generator.....	3-103
<u>3.3.17</u>	Suppression Pool Temperature Monitoring System.....	3-121
<u>3.3.18</u>	Cranes and Hoists	3-122

<u>3.4</u>	AGING MANAGEMENT OF STEAM AND POWER CONVERSION SYSTEMS	3-123
<u>3.4.1</u>	Main Steam System	3-124
<u>3.4.2</u>	Main Condenser	3-128
<u>3.4.3</u>	Feedwater System	3-129
<u>3.5</u>	AGING MANAGEMENT OF STRUCTURES AND COMPONENT SUPPORTS	3-130
<u>3.5.1</u>	Containment Structure	3-131
<u>3.5.2</u>	Reactor Building Structure	3-134
<u>3.5.3</u>	Radwaste Building and Reactor Auxiliary Bay	3-137
<u>3.5.4</u>	Turbine Building and Main Control Room Complex	3-139
<u>3.5.5</u>	Emergency Cooling Tower and Reservoir	3-140
<u>3.5.6</u>	Station Blackout Structure and Foundations	3-141
<u>3.5.7</u>	Yard Structures	3-142
<u>3.5.8</u>	Stack	3-143
<u>3.5.9</u>	Nitrogen Storage Building	3-144
<u>3.5.10</u>	Diesel Generator Building	3-145
<u>3.5.11</u>	Circulating Water Pump Structure	3-146
<u>3.5.12</u>	Recombiner Building	3-147
<u>3.5.13</u>	Component Supports	3-148
<u>3.5.14</u>	Hazard Barriers and Elastomers	3-150
<u>3.5.15</u>	Miscellaneous Steel	3-154
<u>3.5.16</u>	Electrical and Instrumentation Enclosures and Raceways	3-155
<u>3.5.17</u>	Insulation	3-156
<u>3.6</u>	AGING MANAGEMENT OF ELECTRICAL AND INSTRUMENTATION AND CONTROLS	3-157
<u>3.6.1</u>	Cables	3-158
<u>3.6.2</u>	Connectors, Splices, and Terminal Blocks	3-159
<u>3.6.3</u>	Station Blackout System	3-160

List of Tables

<u>3.1-1</u>	Aging Management Review Results for Component Groups for the Reactor Pressure Vessel and Internals	3-10
<u>3.1-2</u>	Aging Management Review Results for Component Groups for Fuel Assemblies	3-14
<u>3.1-3</u>	Aging Management Review Results for Component Groups for the Reactor Pressure Vessel Instrumentation	3-15
<u>3.1-4</u>	Aging Management Review Results for Component Groups in the Reactor Recirculation System.....	3-17
<u>3.2-1</u>	Aging Management Review Results for Component Groups in the High Pressure Coolant Injection System	3-20
<u>3.2-2</u>	Aging Management Review Results for Component Groups in the Core Spray System.....	3-33
<u>3.2-3</u>	Aging Management Review Results for Component Groups in the Primary Containment Isolation System	3-41
<u>3.2-4</u>	Aging Management Review Results for Component Groups in the Reactor Core Isolation Cooling System	3-44
<u>3.2-5</u>	Aging Management Review Results for Component Groups in the Residual Heat Removal System	3-54
<u>3.2-6</u>	Aging Management Review Results for Component Groups in the Containment Atmosphere Control and Dilution System.....	3-62
<u>3.2-7</u>	Aging Management Review Results for Component Groups in the Standby Gas Treatment System	3-64
<u>3.2-8</u>	Aging Management Review Results for Component Groups in the Secondary Containment	3-66
<u>3.3-1</u>	Aging Management Review Results for Component Groups in the Fuel Handling System	3-68
<u>3.3-2</u>	Aging Management Review Results for Component Groups in the Fuel Pool Cooling and Cleanup System	3-69
<u>3.3-3</u>	Aging Management Review Results for Component Groups in the Control Rod Drive System	3-70
<u>3.3-4</u>	Aging Management Review Results for Component Groups in the Standby Liquid Control System	3-72
<u>3.3-5</u>	Aging Management Review Results for Component Groups in the High Pressure Service Water System	3-74
<u>3.3-6</u>	Aging Management Review Results for Component Groups in the Emergency Service Water System	3-79
<u>3.3-7</u>	Aging Management Review Results for Component Groups in the Fire Protection System.....	3-82
<u>3.3-8</u>	Aging Management Review Results for Component Groups in the Control Room Ventilation System	3-90
<u>3.3-9</u>	Aging Management Review Results for Component Groups in the Battery and Emergency Switchgear Ventilation System	3-92

<u>3.3-10</u>	Aging Management Review Results for Component Groups in the Diesel Generator Building Ventilation System	3-94
<u>3.3-11</u>	Aging Management Review Results for Component Groups in the Pump Structure Ventilation System	3-95
<u>3.3-12</u>	Aging Management Review Results for Component Groups in the Safety Grade Instrument Gas	3-96
<u>3.3-13</u>	Aging Management Review Results for Component Groups in the Backup Nitrogen to ADS System	3-97
<u>3.3-14</u>	Aging Management Review Results for Component Groups in the Emergency Cooling Water System	3-98
<u>3.3-15</u>	Aging Management Review Results for Component Groups in the Condensate Storage System	3-101
<u>3.3-16</u>	Aging Management Review Results for Component Groups for the Emergency Diesel Generator	3-103
<u>3.3-17</u>	Aging Management Review Results for Component Groups in the Suppression Pool Temperature Monitoring System.....	3-121
<u>3.3-18</u>	Aging Management Review Results for Component Groups for Cranes and Hoists	3-122
<u>3.4-1</u>	Aging Management Review Results for Component Groups in the Main Steam System.....	3-124
<u>3.4-2</u>	Aging Management Review Results for Component Groups in the Main Condenser System.....	3-128
<u>3.4-3</u>	Aging Management Review Results for Component Groups in the Feedwater System	3-129
<u>3.5-1</u>	Aging Management Review Results for Component Groups in the Containment Structure	3-131
<u>3.5-2</u>	Aging Management Review Results for Component Groups in the Reactor Building Structure	3-134
<u>3.5-3</u>	Aging Management Review Results for Component Groups in the Radwaste Building and Reactor Auxiliary Bay	3-137
<u>3.5-4</u>	Aging Management Review Results for Component Groups in the Turbine Building and Main Control Room Complex	3-139
<u>3.5-5</u>	Aging Management Review Results for Component Groups in the Emergency Cooling Tower and Reservoir	3-140
<u>3.5-6</u>	Aging Management Review Results for Component Groups in the Station Blackout Structure and Foundation	3-141
<u>3.5-7</u>	Aging Management Review Results for Component Groups in the Yard Structures	3-142
<u>3.5-8</u>	Aging Management Review Results for Component Groups in the Stack.....	3-143
<u>3.5-9</u>	Aging Management Review Results for Component Groups in the Nitrogen Storage Building	3-144
<u>3.5-10</u>	Aging Management Review Results for Component Groups in the Diesel Generator Building	3-145

Table of Contents

<u>3.5-11</u>	Aging Management Review Results for Component Groups in the Circulating Water Pump Structure	3-146
<u>3.5-12</u>	Aging Management Review Results for Component Groups in the Recombiner Building.....	3-147
<u>3.5-13</u>	Aging Management Review Results for Component Supports ..	3-148
<u>3.5-14</u>	Aging Management Review Results for Hazard Barriers and Elastomers.....	3-150
<u>3.5-15</u>	Aging Management Review Results for Miscellaneous Steel.....	3-154
<u>3.5-16</u>	Aging Management Review Results for Electrical and Instrumentation Enclosures and Raceways.....	3-155
<u>3.5-17</u>	Aging Management Review Results for Insulation	3-156
<u>3.6-1</u>	Aging Management Review Results for Cables.....	3-158
<u>3.6-2</u>	Aging Management Review Results for Connectors, Splices and Terminal Blocks.....	3-159
<u>3.6-3</u>	Aging Management Review Results for Station Blackout System.....	3-160

List of Figures

<u>3-0-1</u>	Correlation of Six Column Tables to Sections in the Application	3-8
--------------	--	-----

SECTION 4.0 TIME-LIMITED AGING ANALYSES

<u>4.1</u>	INTRODUCTION.....	4-1
<u>4.1.1</u>	Identification of TLAAs	4-2
<u>4.1.2</u>	Summary of Results.....	4-3
<u>4.1.3</u>	Identification of Exemptions	4-8
<u>4.2</u>	REACTOR VESSEL NEUTRON EMBRITTLEMENT.....	4-9
<u>4.2.1</u>	10CFR50 Appendix G Reactor Vessel Rapid Failure Propagation and Brittle Fracture Considerations: Charpy Upper-Shelf Energy (USE) Reduction and RT _{NDT} Increase	4-10
<u>4.2.2</u>	Reactor Vessel Thermal Limit Analyses: Operating Pressure- Temperature Limit Curves.....	4-11
<u>4.2.3</u>	Reactor Vessel Circumferential Weld Examination Relief	4-12
<u>4.2.4</u>	Reactor Vessel Axial Weld Failure Probability	4-13
<u>4.3</u>	METAL FATIGUE	4-14
<u>4.3.1</u>	Reactor Vessel Fatigue	4-14
<u>4.3.2</u>	Reactor Vessel Internals Fatigue and Embrittlement	4-17
<u>4.3.3</u>	Piping and Component Fatigue and Thermal Cycles	4-21
<u>4.3.4</u>	Effects of Reactor Coolant Environment on Fatigue Life of Components and Piping (Generic Safety Issue 190)	4-24
<u>4.4</u>	ENVIRONMENTAL QUALIFICATION OF ELECTRICAL EQUIPMENT (EQ)	4-32
<u>4.4.1</u>	Electrical Equipment Environmental Qualification Analyses.....	4-32
<u>4.4.2</u>	GSI-168, Environmental Qualification of Electrical Components	4-35
<u>4.5</u>	LOSS OF PRESTRESS IN CONCRETE CONTAINMENT TENDONS (NOT APPLICABLE).....	4-36
<u>4.6</u>	CONTAINMENT FATIGUE.....	4-37
<u>4.6.1</u>	Fatigue Analyses of Containment Pressure Boundaries: Analysis of Tori, Torus Vents, and Torus Penetrations.....	4-38
<u>4.6.2</u>	Fatigue Analysis of SRV Discharge Lines and External Torus-Attached Piping	4-40
<u>4.6.3</u>	Expansion Joint and Bellows Fatigue Analyses - Drywell to Torus Vent Bellows	4-41
<u>4.6.4</u>	Expansion Joint and Bellows Fatigue Analyses - Containment Process Penetration Bellows	4-42

<u>4.7</u>	METAL CORROSION ALLOWANCES	4-43
<u>4.7.1</u>	Reactor Vessel Corrosion Allowances.....	4-43
<u>4.7.2</u>	Corrosion Allowances for ASME VIII Vessels: RHR Heat Exchangers	4-44
<u>4.7.3</u>	Corrosion Allowances fro MSIVs	4-45
<u>4.7.4</u>	Corrosion Allowances for Recirculation Pump Casings.....	4-46
<u>4.7.5</u>	Corrosion Allowance for GE-Scope Nuclear Group I, II, and III Carbon Steel Piping	4-47
<u>4.8</u>	INSERVICE FLAW GROWTH ANALYSES THAT DEMONSTRATE STRUCTURAL INTEGRITY FOR 40 YEARS	4-48
<u>4.8.1</u>	Generic Letter 81-11 Crack Growth Analysis to Demonstrate Conformance to the Intent of NUREG-0619, "BWR Feedwater Nozzle and Control Rod Drive Return Line Nozzle Cracking"	4-49
<u>4.8.2</u>	Fracture Mechanics of ISI-Reportable Indications for Group I Piping: As-forged laminar tear in a Unit 3 Class 1 main steam elbow near weld 1-B-3BC-LDO discovered during preservice UT	4-51
<u>4.9</u>	INSERVICE LOCAL METAL CONTAINMENT CORROSION ANALYSES	4-52
<u>4.10</u>	HIGH-ENERGY LINE BREAK POSTULATION BASED ON FATIGUE CUMULATIVE USAGE FACTOR.....	4-53
<u>4.11</u>	REFERENCES FOR SECTION 4.....	4-54

List of Tables

4.1-1 List of Time-Limited Aging Analyses..... 4-4

4.3.1-1 FatiguePro Monitoring Locations 4-16

4.3.4-1 Design Basis Plant Transient Comparison for the BWR-4 in EPRI
Report No. TR-110356 vs. PBAPS 4-29

4.3.4-2 FatiguePro Monitoring Locations 4-30

4.3.4-3 FatiguePro Monitoring Locations 4-31

APPENDIX A UPDATED FINAL SAFETY ANALYSIS REPORT (UFSAR) SUPPLEMENT

<u>A.1</u>	EXISTING AGING MANAGEMENT ACTIVITIES	A-3
<u>A.1.1</u>	Flow Accelerated Corrosion Program	A-3
<u>A.1.2</u>	Reactor Coolant System Chemistry	A-3
<u>A.1.3</u>	Closed Cooling Water Chemistry	A-4
<u>A.1.4</u>	Condensate Storage Tank Chemistry Activities	A-4
<u>A.1.5</u>	Torus Water Chemistry Activities	A-4
<u>A.1.6</u>	Fuel Pool Chemistry Activities	A-4
<u>A.1.7</u>	High Pressure Service Water Radioactivity Monitoring Activities	A-5
<u>A.1.8</u>	Inservice Inspection (ISI) Program	A-5
<u>A.1.9</u>	Primary Containment Inservice Inspection Program	A-5
<u>A.1.10</u>	Primary Containment Leakage Rate Testing Program	A-5
<u>A.1.11</u>	Inservice Testing (IST) Program	A-6
<u>A.1.12</u>	Reactor Materials Surveillance Program	A-6
<u>A.1.13</u>	Standby Liquid Control System Surveillance Activities	A-6
<u>A.1.14</u>	Crane Inspection Activities	A-7
<u>A.1.15</u>	Conowingo Hydroelectric Plant (Dam) Aging Management Program	A-7
<u>A.1.16</u>	Heat Exchanger Inspection Activities	A-7
<u>A.1.17</u>	Maintenance Rule Structural Monitoring Program	A-7
<u>A.2</u>	ENHANCED AGING MANAGEMENT ACTIVITIES	A-9
<u>A.2.1</u>	Lubricating and Fuel Oil Quality Testing Activities	A-9
<u>A.2.2</u>	Boraflex Management Activities	A-9
<u>A.2.3</u>	Ventilation System Inspection and Testing Activities	A-9
<u>A.2.4</u>	Emergency Diesel Generator Testing and Inspection Activities	A-9
<u>A.2.5</u>	Outdoor, Buried, and Submerged Component Inspection Activities	A-10
<u>A.2.6</u>	Door Inspection Activities	A-11
<u>A.2.7</u>	Reactor Pressure Vessel and Internals ISI Program	A-11
<u>A.2.8</u>	Generic Letter 89-13 Activities	A-12
<u>A.2.9</u>	Fire Protection Activities	A-12
<u>A.2.10</u>	HPCI and RCIC Turbine Inspection Activities	A-12
<u>A.2.11</u>	Susquehanna Substation Wooden Pole Inspection Activity	A-13

Table of Contents

<u>A.3</u>	NEW AGING MANAGEMENT ACTIVITIES.....	A-14
<u>A.3.1</u>	Torus Piping Inspection Activities	A-14
<u>A.3.2</u>	FSSD Cable Inspection Activity	A-14
<u>A.4</u>	TIME-LIMITED AGING ANALYSES ACTIVITIES	A-15
<u>A.4.1</u>	Environmental Qualification Activities	A-15
<u>A.4.2</u>	Fatigue Management Activities	A-15
<u>A.5</u>	TIME-LIMITED AGING ANALYSES SUMMARIES	A-16
<u>A.5.1</u>	Reactor Vessel Neutron Embrittlement	A-16
<u>A.5.2</u>	Metal Fatigue	A-17
<u>A.5.3</u>	Environmental Qualification of Electrical Equipment	A-21
<u>A.5.4</u>	Containment Fatigue	A-21
<u>A.5.5</u>	Metal Corrosion Allowances	A-22
<u>A.5.6</u>	Inservice Flaw Growth Analysis That Demonstrates Structural Integrity for 40 Years	A-24
<u>A.5.7</u>	References for Section A.5	A-25

APPENDIX B AGING MANAGEMENT ACTIVITIES

<u>B.1</u>	EXISTING AGING MANAGEMENT ACTIVITIES	B-2
<u>B.1.1</u>	Flow Accelerated Corrosion Program	B-2
<u>B.1.2</u>	Reactor Coolant System Chemistry	B-5
<u>B.1.3</u>	Closed Cooling Water Chemistry	B-7
<u>B.1.4</u>	Condensate Storage Tank Chemistry Activities	B-9
<u>B.1.5</u>	Torus Water Chemistry Activities	B-11
<u>B.1.6</u>	Fuel Pool Chemistry Activities	B-13
<u>B.1.7</u>	High Pressure Service Water Radioactivity Monitoring Activities	B-15
<u>B.1.8</u>	Inservice Inspection (ISI) Program	B-17
<u>B.1.9</u>	Primary Containment Inservice Inspection Program	B-21
<u>B.1.10</u>	Primary Containment Leakage Rate Testing Program	B-23
<u>B.1.11</u>	Inservice Testing (IST) Program	B-26
<u>B.1.12</u>	Reactor Materials Surveillance Program	B-28
<u>B.1.13</u>	Standby Liquid Control System Surveillance Activities	B-30
<u>B.1.14</u>	Crane Inspection Activities	B-32
<u>B.1.15</u>	Conowingo Hydroelectric Plant (Dam) Aging Management Program	B-34
<u>B.1.16</u>	Heat Exchanger Inspection Activities	B-35
<u>B.1.17</u>	Maintenance Rule Structural Monitoring Program	B-37
 <u>B.2</u>	 ENHANCED AGING MANAGEMENT ACTIVITIES	 B-40
<u>B.2.1</u>	Lubricating and Fuel Oil Quality Testing Activities	B-40
<u>B.2.2</u>	Boraflex Management Activities	B-43
<u>B.2.3</u>	Ventilation System Inspection and Testing Activities	B-45
<u>B.2.4</u>	Emergency Diesel Generator Testing and Inspection Activities	B-48
<u>B.2.5</u>	Outdoor, Buried, and Submerged Component Inspection Activities	B-51
<u>B.2.6</u>	Door Inspection Activities	B-54
<u>B.2.7</u>	Reactor Pressure Vessel and Internals ISI Program	B-56
<u>B.2.8</u>	Generic Letter 89-13 Activities	B-61
<u>B.2.9</u>	Fire Protection Activities	B-64
<u>B.2.10</u>	HPCI and RCIC Turbine Inspection Activities	B-68
<u>B.2.11</u>	Susquehanna Substation Wooden Pole Inspection Activity	B-70
 <u>B.3</u>	 NEW AGING MANAGEMENT ACTIVITIES	 B-72
<u>B.3.1</u>	Torus Piping Inspection Activities	B-72
<u>B.3.2</u>	FSSD Cable Inspection Activity	B-74
 <u>B.4</u>	 TIME-LIMITED AGING ANALYSES ACTIVITIES	 B-76
<u>B.4.1</u>	Environmental Qualification Activities	B-76
<u>B.4.2</u>	Fatigue Management Activities	B-79

APPENDIX C COMMODITY GROUPS (Optional)

Appendix C - Not Used

APPENDIX D TECHNICAL SPECIFICATION CHANGES (Later, if required)

APPENDIX E ENVIRONMENTAL INFORMATION
(Under separate review)