

NRC INSPECTION MANUAL

IIPB

Change Notice 01-020

DELETED:

Number

Date

1. IMC 2620

02/11/93

TRANSMITTED:

Number

Date

IMC 2620

10/05/01

TRAINING: No special training requirements have been identified for any documents issued with this change notice.

REMARKS: IMC 2620 (On-Site Construction Reviews of Remedial Action at Inactive Uranium Mill Tailing Sites (Title I, Uranium Mill Tailing Radiation Control Act)) has been reviewed and revised. Changes were in section 04.02 where the Division of Low-Level Waste Management was changed to Division of Fuel Cycle Safety and Safeguards. Section 04.03 was deleted because the Uranium Recovery Field Office no longer exists. Ownership of this document is now assigned to the, Fuel Cycle Licensing Branch, Division of Fuel Cycle Safety and Safeguards, NMSS.

DISTRIBUTION: Standard

END