



Florida Power & Light Company, 6501 South Ocean Drive, Jensen Beach, FL 34957

December 28, 2001

L-2001-285
10 CFR 50.36
10 CFR 50.4

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Re: St. Lucie Unit 2
Docket No. 50-389
Special Report
Steam Generator Tube Plugging Report

This letter is being sent pursuant to St. Lucie Unit 2 Technical Specification 4.4.5.5.a. The following tubes were plugged during the Unit 2 refueling outage (SL2-13).


Steam Generator 2A - 129
Steam Generator 2B - 232

Cumulative tubes plugged during this outage and previous outages:

Steam Generator 2A - 474
Steam Generator 2B - 539

Should you have any questions on this information, please contact us.

Very truly yours,



Donald E. Jernigan
Vice President
St. Lucie Plant

DEJ/GRM

A001