

From: Brian Holian
To: Bill Bateman, Edmund Sullivan
Date: Wed, Oct 25, 2000 10:26 AM
Subject: paragraph for transmittal ltr

Ted

thanks for the proposal.

We thought it would be better to start with the positive...what is true (as a reminder)...then state nothing changes...

Try this...(for time...I am also soliciting comments from Hub and Jim W. with this email)

"The attached lessons-learned report provides a number of generic technical and process recommendations that apply to the industry and the NRC. There is a recommendation directed to Con Edison which supports the conclusions of the August 31, 2000, NRC Special Inspection Report on the IP2 steam generator tube failure. The lessons-learned report reiterates the significant performance issues (as described in the August 31, 2000, NRC Special Inspection Report) related to how Con Edison implemented its steam generator inspection program during the 1997 plant outage. Principally, those performance issues were associated with the licensee not taking effective actions to react to the conditions found in the steam generators and to compensate for the problems that adversely affected data quality. The lessons-learned report does not in any way modify the conclusions of the special inspection report. The licensee specific deficiencies identified in the special inspection report and any further interactions between NRC and Con Edison relative to those deficiencies are being addressed under the NRC's oversight process."

Ted

can you get me a version of the whole memo...when you insert this...

Thank you
Brian

CC: DCL, HJM1, JTW1, WDL

①

4/40