



DEPARTMENT OF THE NAVY  
OFFICE OF THE CHIEF OF NAVAL OPERATIONS  
2000 NAVY PENTAGON  
WASHINGTON, D.C. 20350-2000

IN REPLY REFER TO

5104  
Ser N455C/2U589683  
February 11, 2002

U.S. Nuclear Regulatory Commission  
Region II  
Atlanta Federal Center  
61 Forsyth St., SW, Suite 23T85  
Atlanta, GA 30303

SUBJECT: NAVAL RADIATION SAFETY COMMITTEE ACTIONS, JANUARY  
CY 2002

In a letter dated April 17, 2000, Nuclear Regulatory Commission Region II requested that the Naval Radiation Safety Committee (NRSC) suspend the practice of submitting copies of NRSC approved permitting actions and inspection reports. As an alternative, it was requested that the NRSC provide the Navy Master Materials License Project Coordinator a monthly summary outlining Naval Radioactive Materials Permit actions and inspection reports approved by the NRSC.

This letter forwards the summary of NRSC approved actions for January 2002. If you have any questions regarding this letter, please contact LT Greg Kahles at (703) 602-2582.

Sincerely,

A handwritten signature in cursive script, reading "D. E. Farrand", is written over the typed name.

D. E. FARRAND

Captain, MSC, U.S. Navy

Executive Secretary

Naval Radiation Safety Committee

Enclosure:

- (1) Naval Radioactive Materials  
Permit Action January 2002

# NAVAL RADIOACTIVE MATERIALS PERMIT

## ACTIONS JANUARY 2002

#	ACTIVITY	PERMIT NUMBER	NEHC RASO	Action	DATE SIGNED	EXPIRES	COMMENTS
1	Naval Shipyard, Norfolk, VA	45-00181-A1NP	RASO	Renewal	02 Jan 02	31 Dec 06	Application Provides Complete Package Including Updated Radiation Safety Program.
2	Navy Mobile Construction Battalion ONE	23-55101-I1NP	RASO	Renewal	02 Jan 02	30 Nov 06	Application Provides Complete Package Including Updated Radiation Safety Program.
3	Material Readiness Battalion, 3D Force Service Support Group, FMF, Pacific	63-29021-C1NP	RASO	Renewal	02 Jan 02	31 Dec 06	Application Provides Complete Package Including Updated Radiation Safety Program.
4	Naval Medical Center, San Diego, CA	04-00259-11NP	NEHC	Inspection	04 Jan 02	N/A	Brachytherapy Quality Management Program Inspection -- 2 Level V Deficiencies Noted.
5	Naval Surface Warfare Center, Dahlgren Division, Dahlgren, VA	45-00178-S1NP	RASO	Termination	04 Jan 02	N/A	Changed to a "Y" Permit to Reflect the Non-Operational Status of the Source Material.
6	Naval Surface Warfare Center, Dahlgren Division, Dahlgren, VA	45-00178-Y1NP	RASO	Issue	04 Jan 02	31 Dec 03	Re-Issue of The "S" Permit Above.
7	Naval Shipyard, Norfolk, VA	45-00181-A1NP	RASO	Inspection	04 Jan 02	N/A	Satisfactory. No Deficiencies Noted.
8	Public Works Center, Washington Navy Yard, Washington, DC	08-68925-J1NP	RASO	Inspection	04 Jan 02	N/A	Satisfactory. Two Severity Level IV and One Severity Level V Deficiency Noted.
9	Naval Submarine Support Facility, New London, CT	06-68316-C1NP	RASO	Amendment	16 Jan 02	31 Aug 06	Designates A New ARSO.
10	Naval Sea Systems Command, Washington, DC	08-00024-T1NP	RASO	Issue	18 Jan 02	30 Jun 02	Formerly NRMP 45-00024-T1NP - Assigns New RSO and Changes the Command's Address.
11	Naval Sea Systems Command, Washington, DC	45-00024-T1NP	RASO	Termination	18 Jan 02		Re-Issued As NRMP 08-00024-T1NP To Reflect New Command Address.
12	Director, Strategic Systems Programs, Washington, DC	08-00030-T1NP	RASO	Amendment	18 Jan 02	31 Mar 03	Names New RSO & ARSO.
13	Naval Surface Warfare Center, Crane Division, Crane, IN	13-00164-Q1NP	RASO	Amendment	18 Jan 02	31 Oct 03	Adds an Irradiator to the Program and Appoints a New RSO.
14	Naval Hospital, Camp Pendleton, CA	04-68094-11NP	NEHC	Amendment	18 Jan 02	31 Dec 05	Incorporates Revised Quality Management Program.
15	Space and Naval Warfare Systems Center, Charleston, SC	39-65236-C1NP	RASO	Termination	18 Jan 02	N/A	Radioactive Materials Have Been Transferred to NRMP No. 39-65236-C2NP.
16	Space and Naval Warfare Systems Center, Charleston, SC	39-65236-C2NP	RASO	Amendment	18 Jan 02	31 May 04	Adds Radioactive Material Transferred From Terminated NRMP No. 39-65236-C1NP.
17	Naval Medical Center, Portsmouth, VA	45-00183-11NP	NEHC	Inspection	23 Jan 02	N/A	Brachytherapy Quality Management Program Inspection -- No Deficiencies Noted.
18	Naval Hospital, Bremerton, WA	46-68095-11NP	NEHC	Amendment	25 Jan 02	31 Aug 03	Adds one Area Authorized For RAM Use, and Makes Minor Administrative Clarifications
19	Naval Medical Center, Portsmouth, VA	45-00183-11NP	NEHC	Amendment	25 Jan 02	31 Mar 02	Added One New AU and Made Minor Administrative Clarifications.
20	Naval Dosimetry Center, Bethesda, MD	19-48539-83NP	NEHC	Inspection	28 Jan 02	N/A	Satisfactory. One Severity Level V Deficiency Noted.
21	Naval Dosimetry Center, Bethesda, MD	19-48539-91NP	NEHC	Inspection	28 Jan 02	N/A	Satisfactory. One Severity Level V Deficiency Noted.
22	Naval Sea Systems Command Detachment, RASO, Yorktown, VA	45-45650-D1NP	RASO	Amendment	29 Jan 02	31 Jan 03	Reissued For A Period Of One Year With Understanding That Project Will Be Completed.
23	31st Naval Construction Regiment, Port Hueneme, CA	04-55752-I1NP	RASO	Inspection	29 Jan 02	N/A	Satisfactory. One Severity Level V Deficiency and One Severity Level IV Deficiency Noted.
24	Naval Research Laboratory	08-00173-E1NP	RASO	Inspection	29 Jan 02	N/A	Satisfactory. One Severity Level IV Deficiency Noted.

# NAVAL RADIOACTIVE MATERIALS PERMIT ACTIONS JANUARY 2002

#	ACTIVITY	PERMIT NUMBER	NEHC RASO	Action	DATE SIGNED	EXPIRES	COMMENTS
25	Naval Air Weapons Station, China Lake, CA	04-60530-B1NP	RASO	Amendment	30 Jan 02	31 Jan 07	Application Provides Complete Package Including Updated Radiation Safety Program.
26	Naval Mobile Construction Battalion FORTY, Port Hueneme, CA	04-55448-I1NP	RASO	Inspection	30 Jan 02	N/A	Satisfactory. One Severity Level V Deficiency and One Severity Level IV Deficiency Noted.
27	Naval Mobile Construction Battalion FORTY, Port Hueneme, CA	04-55448-I1NP	RASO	Amendment	30 Jan 02	28 Feb 07	Application Provides Complete Package Including Updated Radiation Safety Program.
28	Navy Mobile Construction Battalion FIVE, Port Hueneme, CA	04-55115-I1NP	RASO	Inspection	01 Feb 02	N/A	Satisfactory. One Severity Level V Deficiency and Five Severity Level IV Deficiencies Noted.