



AP1000 Shield Building Vertical stresses due to SSE



Slide 31



AP1000 Shield Building close to Openings Vertical stresses due to SSE



Slide 32

