


Mattingly Testing Services, Inc.

P.O. Box 3128
GREAT FALLS, MONTANA 59403
406-284-5471

FAX COVER SHEETDATE/TIME: 6-17-03

PRIORITY:

IMMEDIATELY X1 HOUR 2-4 HOUR MESSAGE TO: Jim MontgomeryMESSAGE FROM: Cheryl DavisonNUMBER OF PAGES: 4 PLUS TRANSMITTAL SHEETFAX TO: 925-673-0112 CONTACT NO: 406-284-5471**SPECIAL INSTRUCTIONS / ATTACHMENTS:**

Jim- Here ~~out~~ are the most recent Leak tests for the four sources that you requested. All leak tests are currently up to date. If you have any further questions, please feel free to call me.

Thanks~
Cheryl Davison



INDUSTRIAL NUCLEAR CO., INC.

TRANSFERRED FROM

MATTINGLY TESTING SERVICES
P.O. BOX 3126
GREAT FALLS, MT 59403

GENTLEMEN

THIS IS TO ADVISE YOU OF A WIPE TEST AND OR SOURCE DISPOSAL

RECEIVED BY I.N.C. ON 10/22/02

IDENTIFICATION

CONTAMINATION

IRIDIUM 192 SOURCE S/N D185

LESS THAN 0.005

INDUSTRIAL NUCLEAR COMPANY

BY MD De

TECHNICIAN

DATE 10/28/02

Any analysis that exhibits a level of contamination of 0.005 microcuries or greater constitutes an incident requiring immediate regulatory notification. As with all notifications, this will be handled by the RSO.

☐ 14320 Wicks Blvd., San Leandro, CA 94577

Tel: (510) 352-6787

Fax: (510) 352-6772

☐ 35 Flagship Dr., North Andover, MA 01845

Tel: (978) 683-5211

Fax: (978) 683-9469

☐ 9125 Airport Blvd., C#10, Houston, TX 77061

Tel: (713) 947-0155

Fax: (713) 947-1384

www. In100.com

e-mail: fenshya@aol.com



LEAK TEST REPORT FORM (MODEL INC-A-REV.1)

Company MATTINGLY TESTING SERVICES
Address P.O. BOX 3126
City GRANT FAMS State MT Zip 59403

ISOTOPE TR-102 + U-238 ACTIVITY 50 CI / 1850.6 ug

Source Serial No. D 968 CAMERA S/N 4486

Smear Taken By Madison DATE 12-31-02

COMMENTS: SAMPLE ALSO ANALYZED FOR DEPLETED URANIUM (U-238)

DIRECTIONS FOR PERFORMING WIPE TEST

1. Moisten swab.
2. Wipe area to be tested (inside exposure port).
3. Replace swab in plastic bag and staple to this page.
4. Complete information requested above
5. Wipe test swab must be returned with this document in a sealed envelope.
6. Ensure that proper survey of swab is performed.

Caution: Conduct a survey on the outside of each package placed in the U.S. Mail. Any envelope or package with a reading in excess of 0.5 mr/hr shall not be mailed

Any analysis that exhibits a level of contamination of 0.005 microcuries or greater constitutes an incident requiring immediate regulatory notification.
10 CFR part 34.25(d)

U-238

40.005

1-10-03

FOR INC USE ONLY

TEST RESULTS

INDUSTRIAL NUCLEAR CO.

WIPE TEST 40.005 μ ci

BY Jan 3

DATE 1-10-03

FORMINC-1

CA OFFICE:

2515 Williams St., San Leandro, CA 94577
Tel: (510) 352-0766-08 • Fax: (510) 352-0772

TX OFFICE:

9125 Airport Blvd., C-10, Houston, TX 77061
Tel: (713) 947-0155, 947-0632 • Fax: (713) 947-1384



INDUSTRIAL NUCLEAR CO., INC.

TRANSFERRED FROM

MATTINGLY TESTING SERVICES
P.O. BOX 3126
GREAT FALLS, MT 59403

GENTLEMEN

THIS IS TO ADVISE YOU OF A WIPE TEST AND OR SOURCE DISPOSAL
RECEIVED BY I.N.C. ON 01/21/03

IDENTIFICATION

CONTAMINATION

IRIDIUM 192 SOURCE S/N D303

LESS THAN 0.005

INDUSTRIAL NUCLEAR COMPANY

BY MD

TECHNICIAN

DATE 01/23/03

Any analysis that exhibits a level of contamination of 0.005 microcuries or greater constitutes an incident requiring immediate regulatory notification. As with all notifications, this will be handled by the RSO.

- 14320 Wicks Blvd., San Leandro, CA 94577
- 35 Flagship Dr., North Andover, MA 01845
- 9126 Airport Blvd., C#10, Houston, TX 77061

www.in100.com

Tel: (510) 382-6767
Tel: (978) 683-5211
Tel: (713) 947-0155

Fax: (510) 382-6772
Fax: (978) 683-9468
Fax: (713) 947-1384



TRANSFERRED FROM

MATTINGLY TESTING SERVICES
P.O. BOX 3126
GREAT FALLS, MT 59403

GENTLEMEN

THIS IS TO ADVISE YOU OF A WIPE TEST AND OR SOURCE DISPOSAL
RECEIVED BY I.N.C. ON 04/14/03

IDENTIFICATION

CONTAMINATION

IRIDIUM 192 SOURCE S/N D702

LESS THAN 0.005

INDUSTRIAL NUCLEAR COMPANY

BY M/S

TECHNICIAN

DATE 04/23/03

Any analysis that exhibits a level of contamination of 0.005 microcuries or greater constitutes an incident requiring immediate regulatory notification. As with all notifications, this will be handled by the RSO.

14320 Wicks Blvd., San Leandro, CA 94577
35 Flagship Dr., North Andover, MA 01845
9125 Airport Blvd., C#10, Houston, TX 77061
www.in100.com

Tel: (510) 352-6767
Tel: (978) 683-5211
Tel: (713) 947-0155

Fax: (510) 352-6772
Fax: (978) 683-9469
Fax: (713) 947-1384