

NOV 17 2003

LR-N03-0466



United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

**STEAM GENERATOR TUBE PLUGGING REPORT
TECHNICAL SPECIFICATION 4.4.6.5.A
SALEM GENERATING STATION UNIT NO. 2
FACILITY OPERATING LICENSE DPR-75
DOCKET NO. 50-311**

Public Service Electric Gas Nuclear, LLC hereby submits the steam generator tube plugging report for Salem Unit No. 2 as required by Technical Specification 4.4.6.5.a for Facility Operating License DPR-75. The Steam Generator Tube in-service inspections were completed on 11/03/03 during the Unit 2, 13th refueling outage.

The following is a summary of the tubes plugged during 2R13 as a result of eddy current inspections:

Steam Generator #21 -	13 tubes
Steam Generator #22 -	11 tubes
Steam Generator #23 -	62 tubes
Steam Generator #24 -	24 tubes

Total Salem Unit No. 2 steam generator tube plugging is 7.54%

Should there be any questions regarding this submittal, please contact Brian Thomas at (856)339-2022.

Sincerely,


Carl Fricker
Plant Manager – Salem

ADCT

NOV 17 2003

C Mr. H. J. Miller, Administrator - Region I
 U. S. Nuclear Regulatory Commission
 475 Allendale Road
 King of Prussia, PA 19406

 U. S. Nuclear Regulatory Commission
 ATTN: Mr. R. Fretz, Licensing Project Manager - Salem
 Mail Stop 08B2
 Washington, DC 20555-0001

 USNRC Senior Resident Inspector - Salem (X24)

 Mr. K. Tosch, Manager IV
 Bureau of Nuclear Engineering
 PO Box 415
 Trenton, NJ 08625