January 29, 2004

MEETING NOTICE

Organization:	Pacific Gas and Electric Company (PG&E)			
Date and Time:	February 12, 2004	8:00 AM (CDT) - 3:00 PM (CDT)		
Location:	The Center for Nuclear Waste Regulatory Analyses (CNWRA) Southwest Research Institute Building 189, Room A-103 6220 Culebra Road San Antonio, TX 78228-5166			
	This meeting will also have a U.S. Nuclear Regula Room O3-B4 11555 Rockville Pike Rockville, MD 20852			
Purpose:	Discuss Pacific Gas & Electric Company's (PG&E's) 10 CFR Part 72 license application for an independent spent fuel storage installation at the Humboldt Bay Power Plant.			
Participants:	<u>NRC/CNWRA</u> Stephen O'Connor Asad Chowdhury (CNWRA)	<u>PG&E</u> Terry Grebel , et al. Larry Pulley, et al.		
Meeting Category:	This is a Category 1 Meeting: The public is invited to observe this meeting and will have one or more opportunities to communicate with the NRC after the business portion, but before the meeting is adjourned as per "Public Meeting Policy," Federal Register Volume 67, Number 102, Pages 36920 - 36924, May 28, 2002.			

Contact: Stephen O'Connor, 301-415-2169

Attendance at this meeting by other than those listed above should be made known by February 10, 2004 via phone to the above contact.

Docket Nos. 72-27, 50-133

TAC No. L23683

Attachment: Agenda

January 29, 2004 MEETING NOTICE

Organization:	Pacific Gas and Electric Company (PG&E)			
Date and Time:	February 12, 2004	8:00 AM (C	DT) - 3:00 PM (CDT)	
Location:	The Center for Nuclear Waste Regulatory Analyses (CNWRA) Southwest Research Institute Building 189, Room A-103 6220 Culebra Road San Antonio, TX 78228-5166			
	This meeting will also have a U.S. Nuclear Regulat Room O3-B4 11555 Rockville Pike Rockville, MD 20852			
Purpose:	Discuss Pacific Gas & Electric Company's (PG&E's) 10 CFR Part 72 license application for an independent spent fuel storage installation at the Humboldt Bay Power Plant.			
Participants:	<u>NRC/CNWRA</u> Stephen O'Connor Asad Chowdhury (CNWRA),	et al.	<u>PG&E</u> Terry Grebel Larry Pulley, et al.	
Meeting Category:	This is a Category 1 Meeting: The public is invited to observe this meeting and will have one or more opportunities to communicate with the NRC after the business portion, but before the meeting is adjourned as per "Public Meeting Policy," Federal Register Volume 67, Number 102, Pages 36920 - 36924, May 28, 2002.			

Contact: Stephen O'Connor, 301-415-2169

Attendance at this meeting by other than those listed above should be made known by February 10, 2004 via phone to the above contact.

Docket Nos. 72-27, 50-133

TAC No. L23683

Attachment: Agenda <u>DISTRIBUTION</u>: NRC File Center SFPO staff (e-mail) AChwdhury, CNWRA

SFPO r/f EWBrach CManepally, CNWRA NMSS r/f PUBLIC WHodges LCamper PMNS (e-mail) WHuffman

C:\ORPCheckout\FileNET\ML040290918.wpd

OFC:	SFPO	SFPO	SFPO	
NAME:	SO'Connor	EZiegler	JMonninger	
DATE:	01/27/04	01/28/04	01/29/04	

Agenda for February 12, 2004, PG&E Meeting with NRC and CNWRA

Introduction	8:00-8:15 (Grebel)	
Overview of Humboldt Bay	8:15-8:20 (Pulley)	
Overview of Spent Fuel	8:20-8:25 (Pulley)	
Licenses and Permits	8:25-8:30 (Grebel)	
Siting Issues	8:30-8:45 (Pulley)	
Geotechnical Overview	8:45-9:30 (Cluff)	
Break	9:30-9:45	
Project Description	9:45-10:30 (Pulley)	
Site-Specific Technical Aspects		
- Seismic / Structural	10:30-11:15 (Pulley / Holtec)	
- Tsunami	11:15-11:30 (Pulley)	
- Fire Hazards	11:30-11:40 (Soenen)	
- Fire Analyses	11:40-12:15 (Holtec)	
Lunch	12:15-1:15	
- Explosion Hazards	1:15-1:25 (Soenen)	
- Explosion Analyses	1:25-1:45 (Holtec)	
- Thermal	1:45-2:00 (Holtec)	
- Criticality	2:00-2:15 (Holtec)	
- Dose	2:15-2:30 (Holtec)	
Summary	2:30-2:45 (Grebel)	