

October 13, 1999

Southeastern Imaging
ATTN: Mr. Dinesh Bhatt, M.D.
President
319 Hospital Drive, Suite 208
Martinsville, VA 24112

SUBJECT: NRC INSPECTION REPORT NO. 45-25272-01/99-01

Dear Mr. Bhatt:

This refers to the inspection conducted on September 16, 1999, at your Martinsville, Virginia facility. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with you.

The inspection was an examination of activities conducted under your license with respect to radiation safety and compliance with NRC regulations and the conditions of your license. It included selective examinations of procedures and representative records, interviews with personnel, and direct observations by the inspector.

Based on the results of this inspection, the NRC has determined that one violation of NRC requirements occurred. This violation is cited in the enclosed NRC Form 591, Part 1, Safety and Compliance Inspection, which is a Notice of Violation (NOV). The inspector described this violation to you at the conclusion of the inspection. Based upon our discussion with you regarding corrective action to prevent re-occurrence of this violation, we understand that in the future you will take alternative measures to ensure that licensed material shall be stored and used only within location as authorized by your license.

You are not required to respond to this letter. However, you are required to read the Statement of Corrective Actions at the bottom of the enclosed NRC Form 591 and sign and date it at the designated location. Please sign and date both copies and return one of the signed forms to the U.S. Nuclear Regulatory Commission, Region II, 61 Forsyth Street SW, Suite 23T85, Atlanta, Georgia, 30303, ATTN: Donna S. Moser.

9910250200 991013
PDR ADOCK 03033303
C PDR

1807

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Sincerely,

TS

Thomas R. Decker, Chief
Materials Licensing/Inspection Branch 1
Division of Nuclear Materials Safety

Docket No. 030-33303
License No. 45-25272-01

Enclosure: NRC Form 591

cc w/encl:
Commonwealth of Virginia

Distribution w/encl:
PUBLIC
RII Docket File, DNMS

OFFICE	RII:DNMS						
SIGNATURE							
NAME	DMoser						
DATE	10/ 4 /99	10/ /99	10/ /99	10/ /99	10/ /99	10/ /99	10/ /99
COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY

DOCUMENT NAME: G:\DNMS\MLIB1\dsm2\letters\030-33303.910

(8-1997)
10 CFR 2.201

SAFETY AND COMPLIANCE INSPECTION

1. LICENSEE

Southeastern Imaging
319 Hospital Drive, Suite 208
Martinsville, VA 24112

2. REGIONAL OFFICE

REGION II
US NUCLEAR REGULATORY COMMISSION
ATLANTA FEDERAL CENTER
61 FORSYTH ST SW STE 23T85
ATLANTA GA 30303-3415

REPORT NUMBER(S) 99-01

3. DOCKET NUMBER(S)

030-33303

4. LICENSE NUMBER(S)

45-25272-01

5. DATE(S) OF INSPECTION

9/16/99

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

non-cited violation(s) were discussed involving the following requirement(s):


- ☒ 3. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which is required to be posted in accordance with 10 CFR 19.11.

License condition 10 A. states that license material shall be stored or used only in the licensee's mobile nuclear medicine unit located on the properties of 314-C East Fairy Street, Martinsville, Virginia.

Contrary to the above license condition, on 9/16/99 the licensee indicated that technicum-99m doses were administered in the offices located at 314-C Fairy Street instead of the mobile unit. In addition, the inspector observed that radioactive waste was also stored for decay in the offices located at 314-C Fairy Street.

STATEMENT OF CORRECTIVE ACTIONS

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE			
NRC INSPECTOR	Donna S. Moser		10/12/1999

(8-1997)
10 CFR 2.201

SAFETY AND COMPLIANCE INSPECTION

1. LICENSEE

**Southeastern Imaging
319 Hospital Drive, Suite 208
Martinsville, VA 24112**

2. REGIONAL OFFICE

**REGION II
US NUCLEAR REGULATORY COMMISSION
ATLANTA FEDERAL CENTER
61 FORSYTH ST SW STE 23T85
ATLANTA GA 30303-3415**REPORT NUMBER(S) **99-01**

3. DOCKET NUMBER(S)

030-33303

4. LICENSE NUMBER(S)

45-25272-01

5. DATE(S) OF INSPECTION

9/16/99

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

non-cited violation(s) were discussed involving the following requirement(s):


- ☒ 3. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which is required to be posted in accordance with 10 CFR 19.11.

License condition 10 A. states that license material shall be stored or used only in the licensee's mobile nuclear medicine unit located on the properties of 314-C East Fairy Street, Martinsville, Virginia.

Contrary to the above license condition, on 9/16/99 the licensee indicated that technicum-99m doses were administered in the offices located at 314-C Fairy Street instead of the mobile unit. In addition, the inspector observed that radioactive waste was also stored for decay in the offices located at 314-C Fairy Street.

STATEMENT OF CORRECTIVE ACTIONS

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE			
NRC INSPECTOR	Donna S. Moser		10/12/1999