

| | | |
|--|--|---------------------------------------|
| TELEPHONE CONVERSATION RECORD | Date: February 4, 2005 | Time: 09:30 |
| Mail Control No.: N/A Inspection No.: N/A | License No.: 45-25268-01 | Docket No.: 030-33271 |
| Person Called: Michael Dickey, Radiation Safety Officer | Licensee: Green Bay Packaging, Inc. | Telephone No.: 540-678-2632 |
| Person Calling: Steven Courtemanche/(610) 337-5075 | | |
| Subject: Information concerning stuck shutter on gauge. | | |
| <p><u>Summary:</u> I left a message on Mr. Dickey's voice-mail for him to get back in touch with me.</p> <p>10:15 Mr. Dickey returned my phone call. He confirmed that a screw had broken in the gauge and jammed the opening mechanism. This was the same cause as Event No. 990305 and it occurred to the same gauge. The gauge was sent back to the manufacturer and replaced with a new gauge of the same type. Mr. Dickey also stated that he wanted to tell me that he had notified NRC Headquarters Operations Officer of another event. It was numbered EN 41345. It involved the malfunction of an on/off switch on one of their gauges. The switch was found to be faulty by a contractor and replaced with a new switch. The gauge was then placed back in service.</p> | | |
| Action Required/Taken: Place into ADAMS. | | |
| Prepared by Steven Courtemanche | Date: February 4, 2005 | |