

TELEPHONE CONVERSATION RECORD	Date: March 2, 2005	Time: 13:40
Mail Control No.: 136490 Inspection No.: N/A	License No.: 29-31017-01	Docket No.: 030-36867
Person Called: Robert J. Tokarz, Consulting Medical Physicist	Licensee: Nuclear Cardiology Diagnostics	Telephone No.: 732-424-0909
Person Calling: Steven Courtemanche/(610) 337-5075		
Subject: License facility status.		
<p><u>Summary:</u> I spoke with Mr. Tokarz about the licensee's facility. He confirmed that the imaging equipment from LN 29-27870-01 would remain in place in Suite 406A. However, the gamma camera in Suite 406A does not have a patient attenuation device and therefore, authorization for materials under 10 CFR 35.500 would not be required. I requested that a diagram showing what is situated in adjacent areas be provided. Mr. Tokarz stated that he would fax in the diagram on Friday morning (March 3). I informed Mr. Tokarz that I would not be able to provide the license to his client until the morning of March 21, 2005, because the current licensee would not be able to finish its operations until late March 18, 2005. I would need to confirm that they are through with the area before I issue the license. Mr. Tokarz stated that he would inform his client.</p>		
Action Required/Taken: Document for ADAMS		
Prepared by Steven Courtemanche	Date: March 2, 2005	