



Danville Diagnostic Imaging Center

125 Executive Drive
Danville, VA 24540
434/793-1043
FAX 434/799-0066

RECEIVED
REGION 1
'05 APR -4 P12:31

US Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406-1415

March 30, 2005

Dear Sir:

03031983

Danville Diagnostic Imaging Center requests a change in NRC license number 45-25118-01 so that we may administer 99m-Techetium Cardiolite in the office of Dr. Stephen Davis, MD, located at 200 Deer Run Road, Danville, VA 24540. In section 10.B.1 of our present license, administration of licensed material in the office of Dr. Stephen is already in place. This notification is being written because Dr. Davis is moving his office to the Deer Run location.

We will continue to comply with the provisions of 10 CFR 35.29, 10 CFR.80 and with provisions stated in previous correspondence.

Enclosed is a letter from Dr. Davis authorizing Danville Diagnostic Imaging Center to administer 99m-Techetium Cardiolite at his office. The office is located on a single story, private building. There are no other occupants in this single office building.

Thank you for this consideration.

Respectfully Submitted,

G. Michael Spencer, MD
Radiation Safety Officer

136811
NMSS/RGNI MATERIALS-002

Stephen Davis, MD
200 Deer Run Road
Danville, VA 24540

March 30, 2005

US Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406-1415

Dear Sir:

I grant approval to Danville Diagnostic Imaging Center for the use of radioactive 99m-Technetium Cardiolite at my office located at 200 Deer Run Road, Danville, VA 24540. Our office does not have an active NRC license. This notification is due to the fact that I am moving my office to a new location. My adult cardiology practice will be the only occupant in this single story building.

I understand that I am under no obligation to have these studies performed in my office but my approval will allow the administration of 99m-Technetium in conjunction with stress testing and subsequent myocardial scanning at Danville Diagnostic Imaging Center, should I desire such examinations, and should the US NRC grant Danville Diagnostic Imaging Center approval to perform such examinations.

Sincerely,


Stephen Davis, MD

This is to acknowledge the receipt of your letter/application dated

3/30/2005, and to inform you that the initial processing which includes an administrative review has been performed.

☒ Amendment 45-25118-01
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

☐ Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 136811.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.

BETWEEN:

License Fee Management Branch, ARM
and
Regional Licensing Sections

(FOR LFMS USE)
INFORMATION FROM LTS

Program Code: 02200
Status Code: 0
Fee Category: 7C
Exp. Date: 20051130
Fee Comments: _____
Decom Fin Assur Req'd: N
.....

LICENSE FEE TRANSMITTAL

A. REGION I

1. APPLICATION ATTACHED

Applicant/Licensee: DANVILLE DIAGNOSTIC IMAGING CENTER
Received Date: 20050404
Docket No: 3031883
Control No.: 136811
License No.: 45-25118-01
Action Type: Amendment

2. FEE ATTACHED

Amount: /
Check No.: _____

3. COMMENTS

Signed *Referee Jones*
Date 4/14/2005

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered /__/)

1. Fee Category and Amount: _____

2. Correct Fee Paid. Application may be processed for:

Amendment _____
Renewal _____
License _____

3. OTHER _____

Signed _____
Date _____