

PAL Diagnostic Center

MS 16
P-1

May 13, 2005

Docket No. 03036446

License No. 37-30854-01

Control # 136637

03036446

James P. Dwyer, Chief
Commercial and R & D Branch
Division of Nuclear Materials Safety
U.S. N.R.C. Region 1
475 Allendale Road
King of Prussia, PA 19406-1415

SUBJECT: Response of letter dated April 27, 2005, Control # 136637

Dear Mr. Dwyer:

This in reference to your letter dated April 27, 2005, requesting additional information for the amendment request for license number 37-30854-01.

- a. Provide a complete description of the transaction (transfer of stocks or assets, or merger)

We are requesting to change the name of the facility only. There is no ownership change, transfer of stocks or merger.

- b. Indicate whether the name has changed and include the new name, Include the name and telephone number of a license contact who NRC may contact if more information is needed.

The new name of the licensed organization is PAL Diagnostic Center

The new license contact and telephone number(s) to facilitate communications is Kim E Zadeh, Practice Manager or Jack Olley, recently contracted consultant physicist (717) 291-9813 voice # 3.

- c. Describe any changes in personnel or duties that relate to the licensed program. Include training and experience of any new personnel.

Paul Collura, M.D is designated as the Radiation Safety Officer. Dr. Collura is currently the Radiation Safety Officer at Lancaster Regional Medical Center (radioactive material license #37-01580-04 belonging to Rose City HMA, Inc. d/b/a Lancaster Regional Medical Center). 136637



The following physicians are our authorize users:

- | | |
|-----------------------------|----------------|
| 1. Alan Alexander, M.D. | - 35.100, 200 |
| 2. Paul Collura, M.D. | - 35.100, 200 |
| 4. Jeffrey Packer, M.D. | - 35.100, 200 |
| 5. Peter R. Smith, M.D. | - 35.100, 200 |
| 6. Robert Springer, M.D. | - 35.100, 200 |
| 7. Peter M. Stillwell, M.D. | - 35.100, 200 |
| 8. Richard Weismer, M.D. | -- 35.100, 200 |

The above physicians are currently on the Lancaster Regional Medical Center's license (#37-01580-04).

- d. Describe any changes in the organization, location, facilities, equipment or procedures that relate to the licensed program.

There are no plans of changes in location, facility, equipment, or procedures, including emergency procedures.

- e. Describe the status of the surveillance program (surveys, wipe tests, quality control) at the present time and the expected status at the time that control is to be transferred.

All records of surveillance items including calibrations, leak tests, radiation surveys, inventories, and accountability logs will be maintained. There are no changes in the radiation safety program.

- f. Confirm that records concerning the safe and effective decommission of the facility will be transferred to the transferee or to NRC, as appropriate. These records include documentation of surveys of ambient radiation levels are fixed and/or removable contamination, including methods and sensitivity.

All records concerning the safe and effective decommission of the facility are still in place.

- g. Confirm that the transferee will abide by all constraints, conditions, requirements and commitments of the transferor or that the transferee will submit a complete description of the proposed licensed program.


Facility is not involved in a transfer.

- ii If your license requires financial assurance for decommissioning, you will need to address changes to financial assurance for name changes and/or change in ownership (control).

There are adequate funds available should the facility require decommissioning.

I have reviewed the application and concur in the statements and representations contained therein.

Sincerely

A handwritten signature in black ink, appearing to be 'Lee Meyers', with a horizontal line extending to the right.

Lee Meyers
CEO, Physicians Alliance