

U.S. NUCLEAR REGULATORY COMMISSION		Date: June 23, 2005
TELEPHONE CONVERSATION RECORD		Time: 1535
Mail Control or Report No(s).	136357	License No(s). 52-21175-01
		Docket No(s). 03019882
Name of Licensee: Baxter Healthcare Corporation		
Name of Participant(s): Angel Alicea (RSO) and Evet Vera		
Telephone No. 787-735-8021		
Subject: Followup to Baxter Response Received June 20. 2005 <small>(NOTE: This will be used as the Documents Title in ADAMS)</small>		
Summary: Two items were discussed with Baxter personnel regarding the Baxter response provided to NRC letter dated May 17, 2005.		
1) It was confirmed that the RSO will be a qualified, trained operator.		
2) A typographical errors exist in the Deionizer Monitor Alarm Procedure, Procedure GAMMA-1. This procedure erroneously refers to the "Deionizer Monitor" as the "Outlet Monitor". The RSO stated that the procedure error will be corrected. Since this type procedure change is allowed without NRC concurrence (10 CFR 36.53(c)), no additional information is needed by the NRC at this time to support completion of the license renewal.		
Action Required:		
Prepared By: James Schmidt		Date: June 27, 2005