

DSER Section Table of Contents

Page, Section, and Paragraph	DSER Text	Suggested Revision	Justification	Category
Page 6-v		Add the following text 2.1.4 Conclusion page.....2-25		3
Page 6-v	2.3.1.1 Class 1 Piping/eomponents System...	2.3.1.1 Class 1 Piping/ C omponents System...		3
Page 6-vii	2.5.1.6 High-voltage Insulators	2.5.1.6 High- V oltage Insulators		3
Page 6-viii	3.0.3.3 AMPs That Are Not Consistent with or Not Addressed in the GALL Report	3.0.3.3 AMPs That Are Not Consistent W ith or Not Addressed in the GALL Report		3
Page 6-viii	3.1.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Not Recommended . .	3.1.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Not Recommended . .		3
Page 6-viii		Add the following text 3.1.2.2 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Recommended....3-139		3
Page 6-viii		Add the following text 3.1.3 Conclusion...3-166		3

Page, Section, and Paragraph	DSER Text	Suggested Revision	Justification	Category
Page 6-viii		Add the following text 3.2.2.2 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Recommended....3-171		3
Page 6-viii	3.3.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Not Recommended . .	3.3.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Not Recommended . .		3
Page 6-viii	3.3.2.2 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Recommended . .	3.3.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Not Recommended . .		3
Page 6-ix	3.5.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Not Recommended . . .	3.5.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Not Recommended . . .		3
Page 6-ix	3.5.2.3 AMR Results That Are Not Consistent with or Not Addressed in the GALL Report	3.5.2.3 AMR Results That Are Not Consistent With or Not Addressed in the GALL Report		3

Page, Section, and Paragraph	DSER Text	Suggested Revision	Justification	Category
Page 6-ix	3.6.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Not Recommended . . .	3.6.2.1 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Not Recommended . . .		3
Page 6-ix	3.6.2.2 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation Is Recommended . . .	3.6.2.2 AMR Results That Are Consistent with the GALL Report, for Which Further Evaluation is Recommended . . .		3
Page 6-ix		Add the following text 3.7 Conclusion for Aging Management...3-303		3
Page 6-xii		Add the following text 4.5 Loss of Preload...4-60 4.5.1 Containment Tendon Loss of Preload...4-60 4.5.1.1 Summary of Technical Information in the Application...4-60 4.5.1.2 Staff Evaluation 4-60 4.5.1.3 FSAR Supplement...4-63		3

Page, Section, and Paragraph	DSER Text	Suggested Revision	Justification	Category
Page 6-xii	4.8.1.4 Conclusion 4-70	4.8.1.4 Conclusion 4-71		3
Page 6-xii		Add the following text 4.9 Conclusion for Time-Limited Aging Analyses...4-71		3
Page 6-xx	STP Steam Trap	STP- Sewage Treatment Plant	Clarification	2