



October 21, 2005

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Serial No. 05-716
NLOS/vlh
Docket No. 50-339
License No. NPF-7

VIRGINIA ELECTRIC AND POWER COMPANY
NORTH ANNA POWER STATION UNIT 2
STEAM GENERATOR TUBE PLUGGING REPORT

Scheduled eddy current inspections of the North Anna Unit 2 "B" steam generator were completed during the Fall 2005 Refueling Outage. In accordance with North Anna Power Station Technical Specifications, Reporting Requirement 5.6.7.a, this letter provides notification that no steam generator tubes were plugged during the outage.

This letter intends no new commitments. If you should have any questions or require additional information, please contact Mr. Thomas Shaub at (804) 273-2763.

Very truly yours,

A handwritten signature in black ink, appearing to read "C. L. Funderburk", is written over a large, loopy circular flourish.

C. L. Funderburk, Director
Nuclear Licensing and Operations Support
Dominion Resources Services, Inc. for
Virginia Electric and Power Company

cc: U. S. Nuclear Regulatory Commission
Region II
Sam Nunn Atlanta Federal Center
61 Forsyth Street, SW
Suite 23T85
Atlanta, Georgia 30303

Mr. Stephen R. Monarque
NRC Project Manager – Surry and North Anna
U. S. Nuclear Regulatory Commission
One White Flint North
11555 Rockville Pike
Rockville, Maryland 20852

Mr. J. E. Reasor, Jr.
Old Dominion Electric Cooperative
Innsbrook Corporate Center
4201 Dominion Boulevard
Suite 300
Glen Allen, Virginia 23060

Mr. J. T. Reece
NRC Senior Resident Inspector
North Anna Power Station

Mr. M. M. Grace
Authorized Nuclear Inspector
North Anna Power Station