

Closed Generic Communication TACs (PA No. 101122CA/B)

Summary Report (07/01/2005 - 09/30/2005)

TAC NO.	TAC TITLE	STATUS	AGE	TAC CLOSED	LEAD ORG
MC6913	BL: Emergency Preparedness and Response Actions for Security-Based Events (Casto-NSIR/Markley-DIPM)	C	2	07/28/2005	NSIR
MC8254	IN: Containment Sump Clogging (Klein-DE/Hodge-DIPM)	C	1	09/29/2005	DE
MC6735	IN: Failure to Evaluate the Effect of Plant Configuration Changes on the Emergency Plan (Johnson-NSIR/King-DIPM)	C	3	07/28/2005	NSIR
MC5857	IN: Fire in Electrical Distribution Systems and Its Impacts on Security Equipment (Tabatabai-DIPM/)	C	5	07/28/2005	DIPM
MC7994	IN: Inadvertent Reactor Trip and Partial Safety Injection Actuation Due to "Tin Whisker" (Rebstock-DE/Laura-DIPM)	C	2	09/08/2005	DE
MC6230	IN: Nonconservatism in Leakage Detection Sensitivity (Hodge-DIPM/)	C	6	08/17/2005	DIPM
MC5749	IN: Outage Planning and Scheduling Impacts on Risk (Laura-DIPM/)	C	6	07/05/2005	DIPM
MC5890	IN: Potential Turbine Overspeed Due to Load Rejection & Failure of the Turbine Bypass Valves to Open (Tabatabai-DIPM)	W	5	07/26/2005	DIPM
MC6953	IN: San Onofre - Vibration-Induced Failure of Fisher Butterfly Valves (Scarborough-DE/Schmitt-DIPM)	C	5	08/16/2005	DE
MC7572	IN: Summary of Fitness-for-Duty Prog Perf Rpts for CY 2001-2003 (Collins-NSIR/Jung-DIPM)	C	0	07/28/2005	NSIR
MC6708	IN: Switchyard Breakers (Koshy-DE/Laura-DIPM)	C	6	08/10/2005	DE
MC6497	RIS: Clarif of Implementing Guidance for Comp Measures Related to Access Autho Orders (Canady-NSIR/Markley-DIPM)	C	5	08/16/2005	NSIR
MC6655	RIS: Clarifi of Reqmts for Appl of the ASME Code Symbol Stamp on Safety Related Components (Sekerak-DE/Markley-DIPM)	C	6	08/23/2005	DE
MC2262	RIS: GL 91-18, Rev 2-Guidance on Operability & Resol of Degraded & Non-Cnfrming Conditions (Boyce-DIPM/Markley-DIPM)	C	14	09/29/2005	DIPM
MC4220	RIS: Guidance for Establishing and Maintaining a Safety Conscious Work Environment (Jarriel-OE/Markley-DIPM)	C	12	08/30/2005	OE

TAC NO.	TAC TITLE	STATUS	AGE	TAC CLOSED	LEAD ORG
MC5381	RIS: Issuance of NRC Management Directive 8.17, Licensee Complaints Against NRC Employees (Allsopp-DIPM/Markley-DIPM)	C	10	08/24/2005	DIPM
MC6993	RIS: NRC Incident Response and the National Response Plan (Kevern-NSIR/Markley-DIPM)	C	2	07/27/2005	NSIR
MC8177	RIS: Preparation and Scheduling of Operator Licensing Examinations (Barnhill-DIPM/Markley-DIPM)	C	1	09/07/2005	DIPM
MC6736	RIS: Rqmts for Pwr Rx Licensees in Poss of Devices Subj to Gen License Rqmts of 31.5 (Klementowicz-DIPM/Markley-DIPM)	C	3	07/25/2005	DIPM
MC5798	RIS: Transportation of Radioactive Material Quantities of Concern NRC Threat (Foster-NSIR/Markley-DIPM)	C	8	07/25/2005	NSIR