

HQ: Chris Miller
 10 km
 Tony Holden

license needed when we considered - by immediate safety issues.

Region
 Dwight
 Tony, Rone
 Chuck PAVK
 Greg Warner
 Kully K.

TA Brief on Palo Verde

- 6/14/04 - sig. event - fault in transmission line several miles away from PV
- Purpose: Threshold: - provide status on where we are in following
- provide scope of findings in order of priority
- allow ask questions.

TQs: J. Bell, Holahan, etc

- Fault - cascaded into other transmission lines around plant.
- Fault - 7 miles from West using substation
- Fault - faulted in 230 KV transmission system
- Fault - failed to isolate
- caused immediate safety issues
- long term issues - we are following to ensure best response & prepared in the future
- priority of issues for follow up:

- 3 top priority issues for follow up:
 - 1st - EDG V2 not leading to bus
 - 2nd - EDG responses

Ex 2

lost 60 excess & similar problems. - answer: 3/12/03

* how PV setup in terms of EDF & coordinated response was in an event like this

- ① - plans for ongoing follow up answer: business going to do study.
- ② - how much we know at time of AIT decision & how much by team
- ③ - could it have been - other type follow up
- all - great concept.

Information in this record was deleted in accordance with the Freedom of Information Act, exemptions 2
 FOIA-2004-0307 H/4